

HAZARDOUS MATERIALS SURVEY FINAL REPORT

OWNER/CLIENT

Center Joint Unified School District 1851 Heritage Lane Suite 210 Sacramento, CA 95815

CONTACT

Mr. Richard Putnam Director of Facilities

SURVEY ADDRESS

Center Joint Unified School District Office Annex 3243 Center Court Lane Antelope, CA 94843

BUILDINGS SURVEYED

Buildings 1-7 (Per Attached Drawings)

PREPARED BY

Ryan Metzen CAC #17-6120 & CDPH #I/A 07452 Entek Consulting Group, Inc. 4200 Rocklin Road, Suite 7 Rocklin, CA 95677

Entek Project #24-7184

April 29, 2024

LEAD



TABLE OF CONTENTS

Executive Summary
Introduction
Building Description
Asbestos Inspection and Sample Collection Protocols <u>6</u>
Asbestos Bulk Sample Results <u>6</u>
Asbestos Regulatory Requirements
Lead Inspection, Sampling, & Results 9
Lead Regulatory Compliance
Freon and Fluorocarbons
Limitations

Appendices

- A. Asbestos Related Documents
- B. Lead Related Documents
- C. Backup Documents



Executive Summary

The United States Environmental Protection Agency, National Emission Standards for Hazardous Air Pollutants (US EPA NESHAP), 40 CFR Part 61 - Nov. 20, 1990, requires an owner or operator of a demolition or renovation project to thoroughly inspect the affected facility or part of the facility where the demolition or renovation operation will occur for the presence of asbestos-containing materials (ACM) prior to the commencement of that project.

This inspection report was requested by Ms. Terra Carlson with Capitol Program Management on behalf of Mr. Richard Putnam, Director of Facilities, for the Center Joint Unified School District (CJUSD).

The purpose of the inspection was to comply with US EPA NESHAP requirements and the Sacramento Metropolitan Air Quality Management District (SMAQMD) which has jurisdiction for this project site to determine if asbestos containing materials are present which may be impacted during an upcoming roofing renovation project, which will include renovation of seven buildings lat the District Annex located at 3243 Center Court Lane in Antelope, California. It is our understanding the District Annex was constructed in the 1980s.

The attached drawing shows approximate sample locations and also identify those bulk sample materials analyzed and found to contain asbestos greater than 1% with a (+) after the sample number. Materials analyzed and found to contain less than 1% asbestos or reported as none detected have a (-) after each sample number. However, in some cases when several samples of one homogenous material are collected, sometimes not all samples are analyzed by the laboratory. In this instance, if one sample for a homogeneous material is reported as containing asbestos greater than 1%, then the remaining samples in the series that are not analyzed are assumed to contain asbestos greater than 1%. For the purposes of this report, all samples that were not analyzed in a series are assumed to contain asbestos greater than 1% and are identified on the attached drawing with a (+) after the sample number.

Materials are classified in the tables of this report as regulated asbestos containing material (RACM), Category I (CAT-I) or Category II (CAT-II) ACM, or asbestos containing construction material (ACCM), which included collecting multiple samples of some materials. Contractors and other individuals who view the sample locations and associated results indicated with either a (-) or a (+) on the drawing to make determinations take the risk of misidentifying a material and may arrive at determinations which are in direct conflict with the written findings of this report. This use of the drawing and the information provided on it relating to individual sample results in determining if a material does or does not contain asbestos is not recommended.

This is a summary of the report. The report must be read in its entirety, and the reader must review all the detailed information provided in the body of the report prior to making any interpretations, or conclusions pertaining to the information. Any conclusions made by the reader about the information provided in the body of this report which are contradictory or not included in this report are the responsibility of the reader.



Asbestos

On April 24, 2024, Entek conducted a survey specific to seven buildings designated by the Owner's Representative, which included the roofs of all permanent buildings located at the campus as indicated on the diagrams provided to Entek

The results of testing for asbestos during this survey indicate asbestos is present in multiple materials on the roofing systems. A quick summary is detailed in the following bullet points, with specifics pertaining to individual materials found in later sections of this report.

Materials Found to Contain Asbestos:

Buildings 1 through 7

• Penetration Mastic Around Pipe Vents, HVAC, Skylights and Miscellaneous Penetrations - Assumed Greater than 1% asbestos.

*Please note that Entek was not able to safely access the roof due to the pitch of the roof and did not have adequate fall protection installed in order to safely access these materials. Entek personnel were able to identify these roof penetrations from the edges of the roof from a ladder and are assuming these mastics are present due to past experience. Therefore, Entek provided an estimate of total amounts of asbestos mastic present per each building. Buildings 1 through 7 are listed on our site map that is attached that can be referenced for location of the other samples collected.

None of the other materials were reported to contain asbestos. Specifics pertaining to individual materials can be found in later sections of this report.

Lead

Entek investigated existing paints, applied coatings, and flashing in an effort to determine if lead was present in these materials. The material detailed in the following list was found to contain more than 5,000 parts per million (ppm) lead and is classified as lead-based paint (LBP). If more than 100 square feet of this material is impacted by a "trigger task", prior notification to Cal/OSHA will be required.

• Metal Flashing - *Results ranged between 957,468 to 961,051* ppm – *Around all pipes, vents*, and potential HVAC associated.

All other paints and materials were determined not to contain lead above the analysis method detection limit of 100 ppm.

Other Hazardous Materials

Entek did not specifically inspect for mercury containing fluorescent light tubes or light ballast which may contain polychlorinated biphenyls (PCBs) or equipment or systems which may contain Freon or other fluorocarbons. However, due to the age of the school, information pertaining to these materials is included in this report for your use and reference.



Introduction

This report presents results of an asbestos and lead survey performed by Entek which included the materials expected to be impacted by the upcoming roofing project. Entek collected samples from seven buildings. Three of these buildings are a part of the "Base Bid" (which we labeled Buildings 1, 2, and 3). There are four other buildings that were originally labeled as Alternate #1, Alternate #2, Alternate #3, and Alternate #4 (which we labeled Buildings 4, 5, 6, and 7). These buildings are on Center Joint Unified School District's (CJUSD) District Annex, which is located at 3243 Center Court Lane in Antelope, California.

The inspection was conducted by Mr. Gerald Moralez and Mr. Karl Suarez on April 24, 202. Mr. Morzlez is a Cal/OSHA Certified Site Surveillance Technician (CSST) and a California Department of Public Health (CDPH) Lead Sampling Technician. Mr. Suarez is a Cal/OSHA Certified Asbestos Consultant (CAC) and CDPH certified Lead Inspector/Assessor.

Building Description

Buildings 1, 2, and 3 - "Base Bid"

Buildings 1, 2, and 3 are located on the northeastern side of the District Annex location. They are single story structures that appear to have a concrete slab foundation. The exteriors are similar in style, which include stucco siding. The roofs are pitched and comprised of a clay "terra cotta" roof system with black roofing felt underneath. There are several penetrations for vents, HVAC equipment, and skylights that were visible, but Entek could not access safely due to the steep slope of the roof.

Building 4 - "Alternate #1"

Same building description as the Base Bid

Building 5 - "Alternate #2"

Same building description as the Base Bid.

Building 6 - "Alternate #3"

Same building description as the Base Bid

Building 7 - "Alternate #4"

Same building description as the Base Bid



Asbestos Inspection and Sample Collection Protocols

Entek included all specific designated roofing areas Buildings 1 through 7, included in this report, but did not use any demolition methods to look within enclosed wall or ceiling cavities during this investigation. Entek could not safely access the potential penetration mastics associated with the vents, HVAC, skylights, etc. due to the steep slope of the roof.

Bulk samples were collected of various materials suspected to contain asbestos by utilizing a power drill and coring tube, cutting the materials with a razor knife, or use of other appropriate hand tools.

Miscellaneous materials were collected from each homogenous area in a manner sufficient to determine whether the material is or is not ACM as required in 40 CFR Part 763, Asbestos-Containing Materials in Schools; Final Rule and Notice, published October 30, 1987.

Approximate locations of all samples collected during this inspection are indicated on the "Bulk Asbestos Material Analysis Request Form for Entek", which served as the chain of custody for the samples, and on the building diagram(s) attached to this report.

Asbestos Bulk Sample Results

There were several materials observed which are considered "suspect" under US EPA guidelines. Under current US EPA guidelines for conducting building inspections for ACM, all "suspect" materials must be assumed to contain asbestos until otherwise determined by laboratory testing.

The samples of materials suspected of containing asbestos were submitted to Asbestech, a laboratory located in Rancho Cordova, California. These samples were subsequently analyzed by polarized light microscopy (PLM) with dispersion staining.

The US EPA NESHAP and SMAQMD uses the terms Regulated Asbestos Containing Material (RACM), Category I, and Category II when identifying materials which contain asbestos in amounts greater than 1%. Cal/OSHA uses the term Asbestos Containing Material (ACM) for materials containing >1% asbestos and the term Asbestos Containing Construction Material (ACCM) which indicates a manufactured construction material contains greater than 0.1% asbestos by weight by the PLM method. This definition can be found in Title 8, 1529.

A total of 37 bulk samples were collected of all "suspect" materials that could safely be accessed that were observed during this investigation. Some of those samples contained multiple layers which were individually analyzed to determine their asbestos content. Analysis of all samples collected was by PLM with dispersion staining. Results of the analysis are listed in the following tables:



	Suspect Materials Found or Assumed TO Contain Asbestos Center High School					
Sample ID#'s	Suspect Material	Asbestos Content/Type (%) by PLM	Location	NESHAP- Cal/OSHA Classification	Total Estimated Quantity	
*N/A	Roof Penetration Mastics (All Colors)	Assumed Greater Than 1% Asbestos	Roofs of Buildings 1, 2, &3	CAT-II	Approximately 200 Sq	
*N/A	Roof Penetration Mastics (All Colors)	Assumed Greater Than 1% Asbestos	Roof of Building 4 (Alternate #1)	CAT-II	Approximately 100 Sq	
*N/A	Roof Penetration Mastics (All Colors)	Assumed Greater Than 1% Asbestos	Roof of Building 5 (Alternate #2)	CAT-II	Approximately 100 Sq	
*N/A	Roof Penetration Mastics (All Colors)	Assumed Greater Than 1% Asbestos	Roof of Building 6 (Alternate #3)	CAT-II	Approximately 50 Sq	
*N/A	Roof Penetration Mastics (All Colors)	Assumed Greater Than 1% Asbestos	Roof of Building 7 (Alternate #4)	CAT-II	Approximately 100 Sq	

*Please note that Entek could not safely access the roof due to the steep slope of the roof. Entek had to assume there are penetration mastics present and provided a quantity estimate based on what was visible by ladder. If fall protection is provided at a later time, Entek could collect samples at a later time to attempt to determine if asbestos is actually present in these materials. However, for the purposes of this report, all areas around any penetrations into the roofing systems need to be assumed to have asbestos containing mastics/caulking associated with these penetrations.

- NOTE: Any CAT-I or CAT-II materials identified in the previous table which will be subjected to mechanical removal, must be considered RACM for the purposes of notification to SMAQMD and classification of waste. Removal of any CAT-I or CAT-II materials prior to demolition of a building is dependent upon how the materials will be impacted and if the impact will cause the materials to become friable. If any remaining CAT-I or CAT-II materials will become friable they must be removed prior to the initiation of demolition.
- NOTE: Cal/OSHA regulates all materials containing greater than 0.1% asbestos. As a result, impact to materials identified as ACCM and ACM must be performed by properly asbestos trained personnel utilizing appropriate personal protection, work practices, as well as, properly constructed and demarcated work areas or containments, in accordance with Cal/OSHA asbestos



regulations.

The table above provides an estimate of the amount of materials in square feet (Sq.) or linear feet (Ln.). Contractors are responsible for quantifying the exact quantity of materials impacted by the renovation or demolition and shall not rely on the quantities in the above tables.

All other materials that were sampled were reported as not containing asbestos and can be referenced in Appendix A.

All sample number noted in the tables above start with EGG-24-7184

US EPA AHERA uses three terms when determining the classification of a material for the purpose of sampling. These terms include miscellaneous, surfacing, and thermal system insulation (TSI).

<u>Miscellaneous materials</u> are building materials on structural components, structural members or fixtures, such as floor and ceiling tiles, and does not include surfacing material or TSI.

<u>Surfacing materials</u> are materials that are sprayed-on, troweled-on, or otherwise applied to surfaces, such as acoustical plaster on ceiling and fireproofing materials on structural members, or other materials on surfaces for acoustical, fireproofing, or other purposes.

<u>TSI</u> is material applied to pipes, fittings, boilers, breeching, tanks, ducts, or other structural components to prevent heat loss or gain, water condensation, or for other purposes.

The information provided in the tables of this report are for use by the Owner in determining where asbestos containing materials are located, and whether or not any future work may impact those materials. The information is also provided for use by any contractor who may perform work in areas impacting the materials listed in this report, and for use as appropriate by asbestos abatement contractors to provide costs related to work impacting ACM.

Any building materials which are considered "suspect" for containing asbestos which have not been identified in this report must be assumed to contain asbestos in amounts >1% until properly investigated and/or tested.

Materials commonly excluded from being suspected for containing asbestos include, but are not limited to: unwrapped pink and yellow fiberglass insulating materials or products, foam insulation, wood, metal, plastic, or glass. All other types of building materials or coatings on the materials listed above are commonly listed as "suspect" and must be tested prior to impact by a Contractor. Work impacting these untested or newly discovered materials must cease until an investigation can be completed.

Asbestos Regulatory Requirements

US EPA



The property included in this survey report is located in Sacramento County. Sacramento Metropolitan Air Quality Management District (SMAQMD) has been given authority for enforcement of the NESHAP regulations by means of their own rules (Rule 902 Asbestos) in this area.

A demolition is the wrecking, taking out, or burning of any load supporting structural member. A renovation is everything else. Ten day written notification to the US EPA Region IX and SMAQMD is required prior to the performance of any demolition project regardless of asbestos being present or not. This notification would also apply to any renovation project which involves the wrecking, taking out, or burning of any load bearing structural member during a renovation as well.

There is not a sufficient amount of ACM present to require a 10 day notification to the US EPA Region IX, and SMAQMD be submitted prior to starting work which will impact materials identified as RACM or Category I and Category II materials if they are made friable. If more than 160 square feet, 260 linear feet or 35 cubic feet of RACM is planned for removal on the project, formal written notification to US EPA Region IX and SMAQMD is required.

Cal/OSHA

Disturbance of any ACM or ACCM could generate airborne asbestos fibers and would be regulated by Cal/OSHA. Cal/OSHA worker health and safety regulations apply during any disturbance of ACM or ACCM by a person while in the employ of another. This is true regardless of friability or quantity disturbed.

Since it has been determined that none of the materials expected to be impacted during this project contain asbestos, a licensed asbestos contractor, certified by the State of California, and registered with Cal/OSHA is not required for this project.

Lead Inspection, Sampling, & Results

A total of four (4) bulk samples of the painted surfaces and flashing from the roofing areas included in this survey were collected and submitted to MicroTest Laboratories located in Rancho Cordova. These samples were subsequently analyzed by atomic absorption spectrometry (AAS). Results of the analysis are listed in the following tables:

Paints/Coatings/ Materials Determined to be Lead Based Paint (> 5,000 ppm)			
Paint/Coating Color or Lead Component/Location/Quantity Material Content (ppm) Content (ppm)		Component/Location/Quantity	
Metal Flashing (Silver)	957,468 to 961,051	Around Vents/Pipes/HVAC Jacks - Buildings 1-3 - Approximately 25 Roof Jacks and 12 Skylights	
Metal Flashing (Silver)	957,468 to 961,051	Around Vents/Pipes/HVAC Jacks - Building 4 (Alternate #1) - Approximately 6 Roof Jacks	
Metal Flashing (Silver)	957,468 to 961,051	Around Vents/Pipes/HVAC Jacks - Building 5 (Alternate #2)- Approximately 4 Roof Jacks	



Paints/Coatings/ Materials Determined to be Lead Based Paint (> 5,000 ppm)			
Paint/Coating Color orLeadComponent/Location/QuantityMaterialContent (ppm)		Component/Location/Quantity	
Metal Flashing (Silver)	957,468 to 961,051	Around Vents/Pipes/HVAC Jacks - Building 6 (Alternate #3) - Approximately 4 Roof Jacks	
Metal Flashing (Silver)	957,468 to 961,051	Around Vents/Pipes/HVAC Jacks - Building 7 (Alternate #4) - Approximately 6 Roof Jacks	

LBP - Materials/coatings/paints meeting the definition of lead-based paint as defined by the CDPH and the US EPA, currently defined as containing lead in concentrations equal to or greater than 1.0 mg/cm², 5,000 ppm, or 0.5% by weight.

Paints/Coatings/Materials Determined NOT TO Contain Lead (<100 ppm)			
Paint/Coating Color or Material Building Component			
Blue Paint Metal Gutters - All Buildings 1 though 7			
Blue Paint Metal Gutters - All Buildings 1 though 7			

Paints determined "NOT TO" contain lead for the purposes of this report are those samples which when analyzed did not indicate lead to be present at or above the reportable limit for the analysis method used. This reportable limit was 100 parts per million (ppm). As a result, any paints shown "NOT TO" contain lead will not require any special training or work practices related to lead when impacted.

Lead Regulatory Compliance

Any upcoming project which may result in the disturbance of lead containing products or surfaces, but is not intended to remediate a lead hazard or specifically designed to remove LBP to reduce or eliminate a known hazard, would be considered "lead related construction work".

Lead related construction work does not fit the classification of a "lead abatement project" under CDPH Title 17 regulations. "*Abatement*" is defined in Title 17, Division 1, Chapter 8, Article 1 as "any set of measures designed to reduce or eliminate lead hazards or LBP for public and residential buildings, but does not include containment or cleaning." A *lead hazard* is defined in Title 17, Division 1, Chapter 8, Article 1 as "deteriorated LBP, lead contaminated dust, lead contaminated soil, disturbing LBP or presumed LBP without containment, or any other nuisance which may result in persistent and quantifiable lead exposure."

Lead related construction work means any "construction, alteration, painting, demolition, salvage, renovation, repair, or maintenance of any residential or public building, including preparation and cleanup, that, by using or disturbing lead-containing material or soil, may result in significant exposure of adults or children to lead". (Title 17, California Code of Regulations, Division 1, Chapter 8, Article 1).



Currently, Cal/OSHA has not established a definition for LBP, nor have they established minimum concentrations where their regulations do not apply. Cal/OSHA regulates all construction activities involving materials containing lead, including LBP. These regulations are found in CCR, Title 8 Section 1532.1 (§1532.1) Lead in Construction.

Since Cal/OSHA has not established a concentration of lead in a product where their regulations do not apply, any disturbance to products containing lead come under the jurisdiction of Cal/OSHA and their regulations. Disturbance of paints/coatings or materials determined to be LBP may trigger a pre-work notification to Cal/OSHA if "trigger tasks" disturb 100 square feet or more of those paints/coatings or materials. Trigger tasks are described in Title 8 CCR 1532.1.

Freon and Fluorocarbons

Freon and other fluorocarbon products associated with HVAC systems, refrigerators, etc. may be present in or on the exterior of the buildings included in this investigation. Prior to demolition of a structure or removal of existing HVAC systems, refrigerators, or any other type of equipment which typically uses these types of coolant products shall have the coolant materials investigated prior to their demolition and removed from the mechanical systems and recycled in accordance with Cal/EPA requirements.

Limitations

Entek inspected only the specific designated areas identified by the Owner of the buildings to be included in the upcoming project, which did not include all areas of each building's interior and exterior components. This survey is specific to roofing and associated materials found on the seven buildings identified by the district located at the District Annex as indicated in the attached sample diagrams. Please note that Entek was not able to safely access the tops of the roofing systems due to the steep slope of the roof. Therefore, they may be materials present that were not visible to Entek at the time of the survey that may require additional sampling after sufficient fall protection is present.

As a result the information provided in this inspection report may not be used to extend the inspection results to areas not included in this report without additional review and sampling as necessary.

Entek did not perform any destructive sampling to look into ceiling and wall cavities. As a result, it may be possible for materials to be hidden in these areas which are not included in this report.

If any new materials not listed as having been sampled, or listed as assumed for containing asbestos in this report are discovered, the new material must be assumed to contain asbestos until properly inspected and tested for asbestos content.

Entek's policy is to retain a full copy of these written documents for three (3) years once the file is closed. At the end of the 3 year period the written files will be destroyed without further notice. It is suggested copies of the file(s) are maintained as per the District's policy.



Entek will be providing only this electronic copy of the report and its attachments for your use. However, if you would like a hard copy of this report please do not hesitate to ask. Entek will be happy to mail the report upon receipt of your request.

Thank you for choosing Entek for your environmental needs. Please call me at (916) 632-6800 if you have any questions regarding this report.

Prepared by:

Paya Mety

Ryan Metzen President Cal/OSHA #17-6120 CDPH #07452

Appendices

- A. Asbestos Related Documents
- B. Lead Related Documents
- C. Backup Documents

C:\Users\Ryan.Ryan2022\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center JUSD\24-7184 District Annex Roof - AsbPb\Project Letters & Reports\Final Haz Mat Report 4-29-24.wpd



APPENDIX A

ASBESTOS RELATED DOCUMENTS

- Bulk Asbestos Analysis Report From Asbestech
- Bulk Asbestos Material Analysis Request Form for Entek
- Asbestos Bulk Sample Location Drawing
- SMAQMD Asbestos Survey Form
- SMAQMD Demolition/Renovation Form (To be completed by Owner)

Client:

Entek Consulting Group, Inc. 4200 Rocklin Rd., Suite 7 Rocklin, CA 95677 *Job:* 24-7184 Center Joint USD District Office Annex, 3243 Center Court Ln. Antelope, Ca

BULK ASBESTOS ANALYSIS REPORT

LAB JOB # 71134-1 Date/Time Collected: 4/24/24 Date Received: 4/25/24			NVLAP Lab Code 101442- Date Analyzed: 4/29/24
Sample No.	Color/Description	% Type Asbestos	Other Materials
ECG-24-7184- 01A	Clear mastic, SE side bldg. 1	NONE DETECTED	Synthetics
01B	Clear mastic, south side bldg. 1	NONE DETECTED	Synthetics
02A	Red terracotta roofing shingle, SE corner bldg. 1	NONE DETECTED	Granular Mins.
02B	Red terracotta roofing shingle, south side bldg. 1	NONE DETECTED	Granular Mins.
03A	Red roofing mortar, south side bldg. 1	NONE DETECTED	Granular Mins.
03B	Red roofing mortar, east side bldg. 1	NONE DETECTED	Granular Mins.
04A	Gray/white exterior stucco, SW side bldg. 1	NONE DETECTED	Granular Mins.
04B	Gray/white exterior stucco, SE side bldg. 1	NONE DETECTED	Granular Mins.
04C	Gray/white exterior stucco, east side bldg. 1	NONE DETECTED	Granular Mins.
04D	Gray/white exterior stucco, NE corner bldg. 1	NONE DETECTED	Granular Mins.

THE ANALYSIS USES POLARIZED LIGHT MICROSCOPY AND DISPERSION STAINING FOLLOWING E.P.A. METHOD 600/R-93/116. NON-FRIABLE MATERIALS WERE ANALYZED APPLYING THE SAME METHOD. THE LOWER DETECTION LIMIT IS <1 % WITH THE PROVISO THAT PLM MAY NOT DETECT FIBERS <0.25 MICRONS IN DIAMETER THAT MAY BE PRESENT IN SAMPLES SUCH AS FLOOR TILES. IN ACCORDANCE WITH TITLE 22, CCR, SECTION 66261.24(a)(2)(A),THE MCL IS 1 %. SAMPLES WERE NOT COLLECTED BY ASBESTECH. THIS REPORT MUST NOT BE REPRODUCED EXCEPT IN FULL WITHOUT THE APPROVAL OF ASBESTECH. THIS REPORT RELATES ONLY TO THE ITEMS TESTED. THIS REPORT MUST NOT BE USED TO CLAIM PRODUCT ENDORSEMENT BY N.V.L.A.P. OR ANY AGENCY OF THE U.S. GOVERNMENT. ASBESTECH ACCEPTS TECHNICAL RESPONSIBILITY FOR THIS REPORT AND DATE OF ISSUE.

Jem Jangles



Client:

Entek Consulting Group, Inc. 4200 Rocklin Rd., Suite 7 Rocklin, CA 95677

Job:

24-7184 Center Joint USD District Office Annex, 3243 Center Court Ln. Antelope, Ca

BULK ASBESTOS ANALYSIS REPORT

LAB JOB # 71134-2NVLAP Lab CodeDate/Time Collected: 4/24/24NVLAP Lab CodeDate Received: 4/25/24Date Analyzed: 4/				
Sample No.	Color/Description	% Type Asbestos	Other Materials	
ECG-24-7184- 04E	Gray/white exterior stucco, NW side bldg. 1	NONE DETECTED	Granular Mins.	
05A	Black roofing paper under terracotta roofing shingles, SE corner bldg. 1	NONE DETECTED	Tar Binder Fibrous Glass	
05B	Black roofing paper under terracotta roofing shingles, east side bldg. 1	NONE DETECTED	Tar Binder Cellulose	
06A	Black asphaltic roofing w/roofing paper, NE corner bldg. 2	NONE DETECTED	Tar Binder Fibrous Glass	
06B	Black asphaltic roofing w/roofing paper, north side bldg. 2	NONE DETECTED	Tar Binder Fibrous Glass	
07A	Black asphaltic roofing w/ paper under terracotta roofing shingles, NW side bldg. 3	NONE DETECTED	Tar Binder Fibrous Glass	
07B	Black asphaltic roofing w/ paper under terracotta roofing shingles, SW side bldg. 3	NONE DETECTED	Tar Binder Fibrous Glass	
08A THE ANALYSIS USES P	Red terracotta roofing shingles, NW side bldg. 3	NONE DETECTED		

THE ANALYSIS USES POLARIZED LIGHT MICROSCOPY AND DISPERSION STAINING FOLLOWING E.P.A. METHOD 600/R-93/116. NON-FRIABLE MATERIALS WERE ANALYZED APPLYING THE SAME METHOD. THE LOWER DETECTION LIMIT IS <1 % WITH THE PROVISO THAT PLM MAY NOT DETECT FIBERS <0.25 MICRONS IN DIAMETER THAT MAY BE PRESENT IN SAMPLES SUCH AS FLOOR TILES. IN ACCORDANCE WITH TITLE 22, CCR, SECTION 66261.24(a)(2)(A), THE MCL IS 1 %. SAMPLES WERE NOT COLLECTED BY ASBESTECH. THIS REPORT MUST NOT BE REPRODUCED EXCEPT IN FULL WITHOUT THE APPROVAL OF ASBESTECH. THIS REPORT RELATES ONLY TO THE ITEMS TESTED. THIS REPORT MUST NOT BE USED TO CLAIM PRODUCT ENDORSEMENT BY N.V.L.A.P. OR ANY AGENCY OF THE U.S. GOVERNMENT. ASBESTECH ACCEPTS TECHNICAL RESPONSIBILITY FOR THIS REPORT AND DATE OF ISSUE.



NVLAP LAB CODE 101442-0

Client:

Entek Consulting Group, Inc. 4200 Rocklin Rd., Suite 7 Rocklin, CA 95677

Job:

24-7184 Center Joint USD District Office Annex, 3243 Center Court Ln. Antelope, Ca

BULK ASBESTOS ANALYSIS REPORT

LAB JOB # 71134-3 Date/Time Collected: 4/24/24 Date Received: 4/25/24			NVLAP Lab Code 101442 Date Analyzed: 4/29/24
Sample No.	Color/Description	% Type Asbestos	Other Materials
ECG-24-7184- 08B	Red terracotta roofing shingles, west side bldg. 3	NONE DETECTED	Granular Mins.
09A	Black asphaltic roofing w/ paper under terracotta roofing shingles, NW corner bldg. 4	NONE DETECTED	Tar Binder Fibrous Glass
09B	Black asphaltic roofing w/ paper under terracotta roofing shingles, north side bldg. 4	NONE DETECTED	Tar Binder Fibrous Glass
10A	Red terracotta roofing shingles, NW corner bldg. 4	NONE DETECTED	Granular Mins.
10B	Red terracotta roofing shingles, north side bldg. 4	NONE DETECTED	Granular Mins.
11A	Black felt roofing w/ paper under terracotta roofing shingle, SE corner bldg. 5	NONE DETECTED	Tar Binder Cellulose
11B	Black felt roofing w/ paper under terracotta roofing shingle, SE side bldg. 5	NONE DETECTED	Tar Binder Cellulose
12A	Red terracotta roofing shingle, SE corner bldg. 5 OLARIZED LIGHT MICROSCOPY AND DISPERSION STAINING F	NONE DETECTED	Granular Mins.

APPLYING THE SAME METHOD. THE LOWER DETECTION LIMIT IS <1 % WITH THE PROVISO THAT PLM MAY NOT DETECT FIBERS <0.25 MICRONS IN DIAMETER THAT MAY TECHNICAL RESPONSIBILITY FOR THIS REPORT AND DATE OF ISSUE.





Client:

Entek Consulting Group, Inc. 4200 Rocklin Rd., Suite 7 Rocklin, CA 95677 Job:

24-7184 Center Joint USD District Office Annex, 3243 Center Court Ln. Antelope, Ca

BULK ASBESTOS ANALYSIS REPORT

LAB JOB # 71134-4 Date/Time Collected: 4/24/24 Date Received: 4/25/24			NVLAP Lab Code 101442-0 Date Analyzed: 4/29/24
Sample No.	Color/Description	% Type Asbestos	Other Materials
ECG-24-7184- 12B	Red terracotta roofing shingle, SW corner bldg. 5	NONE DETECTED	Granular Mins.
13A	Black remnant roofing paper, SW side bldg. 5	NONE DETECTED	Tar Binder Cellulose
13B	Black remnant roofing paper, south side bldg. 5	NONE DETECTED	Tar Binder Cellulose
14A	Red terracotta roofing shingle, SE corner bldg. 6	NONE DETECTED	Granular Mins.
14B	Red terracotta roofing shingle, SW corner bldg. 6	NONE DETECTED	Granular Mins.
15A	Black remnant roofing paper, SW corner bldg. 6	NONE DETECTED	Tar Binder Fibrous Glass
15B	Black remnant roofing paper, south side bldg. 6	NONE DETECTED	Tar Binder Fibrous Glass
16A	Black felt roofing paper, east side bldg. 7	NONE DETECTED	Tar Binder Cellulose
16B THE ANALYSIS USES P	Black felt roofing paper, west side bldg. 7 olarized light microscopy and dispersion staining fo	NONE DETECTED	Tar Binder Cellulose NON-FRIABLE MATERIALS WERE ANALYZED

THE ANALYSIS USES POLARIZED LIGHT MICROSCOPY AND DISPERSION STAINING FOLLOWING E.P.A. METHOD 600/R-93/116. NON-FRIABLE MATERIALS WERE ANALYZED APPLYING THE SAME METHOD. THE LOWER DETECTION LIMIT IS <1 % WITH THE PROVISO THAT PLM MAY NOT DETECT FIBERS <0.25 MICRONS IN DIAMETER THAT MAY BE PRESENT IN SAMPLES SUCH AS FLOOR TILES. IN ACCORDANCE WITH TITLE 22, CCR, SECTION 66261.24(a)(2)(A),THE MCL IS 1 %. SAMPLES WERE NOT COLLECTED BY ASBESTECH. THIS REPORT MUST NOT BE REPRODUCED EXCEPT IN FULL WITHOUT THE APPROVAL OF ASBESTECH. THIS REPORT RELATES ONLY TO THE ITEMS TESTED. THIS REPORT MUST NOT BE USED TO CLAIM PRODUCT ENDORSEMENT BY N.V.L.A.P. OR ANY AGENCY OF THE U.S. GOVERNMENT. ASBESTECH ACCEPTS TECHNICAL RESPONSIBILITY FOR THIS REPORT AND DATE OF ISSUE.



Client:

Entek Consulting Group, Inc. 4200 Rocklin Rd., Suite 7 Rocklin, CA 95677

Job:

24-7184 Center Joint USD District Office Annex, 3243 Center Court Ln. Antelope, Ca

BULK ASBESTOS ANALYSIS REPORT

LAB JOB # 71134-5 Date/Time Collected: 4/24/24 Date Received: 4/25/24			NVLAP Lab Code 101442-0 Date Analyzed: 4/29/24
Sample No.	Color/Description	% Type Asbestos	Other Materials
ECG-24-7184- 17A	Red terracotta roofing shingles, east side bldg. 7	NONE DETECTED	Granular Mins.
17B	Red terracotta roofing shingles, west side bldg. 7	NONE DETECTED	Granular Mins.

THE ANALYSIS USES POLARIZED LIGHT MICROSCOPY AND DISPERSION STAINING FOLLOWING E.P.A. METHOD 600/R-93/116. NON-FRIABLE MATERIALS WERE ANALYZED APPLYING THE SAME METHOD. THE LOWER DETECTION LIMIT IS <1 % WITH THE PROVISO THAT PLM MAY NOT DETECT FIBERS <0.25 MICRONS IN DIAMETER THAT MAY BE PRESENT IN SAMPLES SUCH AS FLOOR TILES. IN ACCORDANCE WITH TITLE 22, CCR, SECTION 66261.24(a)(2)(A), THE MCL IS 1 %. SAMPLES WERE NOT COLLECTED BY ASBESTECH. THIS REPORT MUST NOT BE REPRODUCED EXCEPT IN FULL WITHOUT THE APPROVAL OF ASBESTECH. THIS REPORT MUST NOT BE USED TO CLAIM PRODUCT ENDORSEMENT BY N.V.L.A.P. OR ANY AGENCY OF THE U.S. GOVERNMENT. ASBESTECH ACCEPTS TOTORING THE DATE OF THE MEMORY OF DETECTION OF THE USED TO CLAIM PRODUCT ENDORSEMENT BY N.V.L.A.P. OR ANY AGENCY OF THE U.S. GOVERNMENT. ASBESTECH ACCEPTS TECHNICAL RESPONSIBILITY FOR THIS REPORT AND DATE OF ISSUE.



NVLAP LAB CODE 101442-0

Jem Jangles



F1134

ENTEK CONSULTING GROUP, INC. 4200 ROCKLIN ROAD, SUITE 7 ROCKLIN, CA 95677 (916) 632-6800 PHONE (916) 632-6812 FAX mainoffice@entekgroup.com

Date of Sampling: 4-24-24

Job Number: 24-7184

Client Name: Center Joint Unified School District

Site Address: District Office Annex 3243 Center Court in 5767 Greenback Lane Antelope, CA 95843 Sacramonto, CA 95841 Lab: Asbestech

Collected by: Gerald Moralez

Turnaround Time: 3-Day, Monday, 4-29-24

ANALYSIS REQUESTED: Asbestos by PLM with Dispersion Staining

Special Instructions: Stop analysis upon first positive result (>1%) for sample in a series. Also stop 19.22 analysis upon first positive result (>1%) in the joint compound for sample series.

Please e-mail results at mainoffice@entekgroup.com and rmetzen@entekgroup.com as soon as available and include copy of submittal with those results.

SAMPLE #	MATERIAL DESCRIPTION/LOCATION
ECG-24-7184-01A	Clear Mastic, Southeast Side, Building 1
ECG-24-7184-01B	Clear Mastic, South Side, Building 1
ECG-24-7184-02A	Red Terracotta Roofing Shingle, Southeast Corner, Building 1
ECG-24-7184-02B	Red Terracotta Roofing Shingle, Southside, Building 1
ECG-24-7184-03A	Red Roofing Mortar, Southside, Building 1
ECG-24-7184-03B	Red Roofing Mortar, Eastside, Building 1
ECG-24-7184-04A	Exterior Grey Stucco, Southwest Side, Building 1
ECG-24-7184-04B	Exterior Grey Stucco, Southeast Side, Building 1
ECG-24-7184-04C	Exterior Grey Stucco, Eastside, Building 1
ECG-24-7184-04D	Exterior Grey Stucco, Northeast Corner, Building 1
ECG-24-7184-04E	Exterior Grey Stucco, Northwest Side, Building 1
ECG-24-7184-05A	Black Roofing Paper under Terracotta Roofing Shingles, Southeast Corner, Building 1

Https://entekgroupinc-my.sharepoint.com/personal/gmoralez_entekgroup_com/Documents/Desktop/Center ASB COC/BLK ASB 4-24-24.docx

Delivered by:

Date: Date:

4/25/24 Time: (0:55 KM/PM 4,25,24 Time: 1055



Received by:



71134

ENTEK CONSULTING GROUP, INC. 4200 ROCKLIN ROAD, SUITE 7 ROCKLIN, CA 95677 (916) 632-6800 PHONE (916) 632-6812 FAX

Date of Sampling: 4-24-24

Job Number: 24-7184

mainoffice@entekgroup.com

Client Name: Center Joint Unified School District

Site Address: District Office Annex

3243 Center Court in 5767 Greenback Lane

Lab: Asbestech

Collected by: Gerald Moralez

Turnaround Time: 3-Day, Monday, 4-29-24

ANALYSIS REQUESTED: Asbestos by PLM with Dispersion Staining

Antelope, CA 95843 Sacramento, CA 95841

Special Instructions: Stop analysis upon first positive result (>1%) for sample in a series. Also stop 79.24 analysis upon first positive result (>1%) in the joint compound for sample series.

Please e-mail results at mainoffice@entekgroup.com and rmetzen@entekgroup.com as soon as available and include copy of submittal with those results.

SAMPLE #	MATERIAL DESCRIPTION/LOCATION		
ECG-24-7184-05B	Black Roofing Paper under Terracotta Roofing Shingles, Eastside, Building 1		
ECG-24-7184-06A	Black Asphaltic Roofing with Roofing Paper, Northeast Corner, Building 2		
ECG-24-7184-06B	Black Asphaltic Roofing with Roofing Paper, Northside, Building 2		
ECG-24-7184-07A	Black Asphaltic Roofing with Paper Under Terracotta Roofing Shingles, Northwest Side, Building 3		
ECG-24-7184-07B	Black Asphaltic Roofing with Paper Under Terracotta Roofing Shingles, Southwest Side, Building 3		
ECG-24-7184-08A	Red Terracotta Roofing Shingles, Northwest Side, Building 3		
ECG-24-7184-08B	Red Terracotta Roofing Shingles, Westside, Building 3		
ECG-24-7184-09A	Black Asphaltic Roofing With Paper Under Terracotta Roofing Shingles, Northwest Corner, Building 4		
ECG-24-7184-09B	Black Asphaltic Roofing With Paper Under Terracotta Roofing Shingles, Northside, Building 4		
ECG-24-7184-10A	Red Terracotta Roofing Shingle, Northwest Corner, Building 4		
ECG-24-7184-10B	Red Terracotta Roofing Shingle, Northside, Building 4		

Https://entekgroupinc-my.sharepoint.com/personal/gmoralez_entekgroup_com/Documents/Desktop/Center ASB COC/BLK ASB 4-24-24.docx

Delivered by:

Date: Date:

4,25,24 Time: 1053

4 1251 24 Time: 10:55 AD1/PM AMIPM

Received by:



71134

ENTEK CONSULTING GROUP, INC. 4200 ROCKLIN ROAD, SUITE 7 ROCKLIN, CA 95677 (916) 632-6800 PHONE (916) 632-6812 FAX mainoffice@entekgroup.com

Date of Sampling: 4-24-24

Job Number: 24-7184

Client Name: Center Joint Unified School District

Site Address: District Office Annex

3243 Center Court in 5767 Greenback Lane Antelope, OA 95343 - Sacramonto, CA 95841

Lab: Asbestech Collected by: Gerald Moralez Turnaround Time: 3-Day, Monday, 4-29-24 ANALYSIS REQUESTED: Asbestos by PLM with Dispersion Staining

JB 429-24 Special Instructions: Stop analysis upon first positive result (>1%) for sample in a series. Also stop analysis upon first positive result (>1%) in the joint compound for sample series.

Please e-mail results at mainoffice@entekgroup.com and rmetzen@entekgroup.com as soon as available and include copy of submittal with those results.

SAMPLE #	MATERIAL DESCRIPTION/LOCATION
ECG-24-7184-11A	Black Felt Roofing paper Under Terracotta Roofing Shingle, Southeast Corner, Building 5
ECG-24-7184-11B	Black Felt Roofing paper Under Terracotta Roofing Shingle, Southeast Side, Building 5
ECG-24-7184-12A	Red Terracotta Roofing Shingle, Southeast Corner, Building 5
ECG-24-7184-12B	Red Terracotta Roofing Shingle, Southwest Corner, Building 5
ECG-24-7184-13A	Black Remnant Roofing Paper, Southwest, Side Building 5
ECG-24-7184-13B	Black Remnant Roofing Paper, Southside, Building 5
ECG-24-7184-14A	Red Terracotta Roofing Shingles, Southeast Corner, Building 6
ECG-24-7184-14B	Red Terracotta Roofing Shingles, Southwest Corner, Building 6
ECG-24-7184-15A	Black Remnant Roofing Paper, Southwest Corner, Building 6
ECG-24-7184-15B	Black Remnant Roofing Paper, South Side, Building 6
ECG-24-7184-16A	Black Felt Roofing Paper, Eastside, Building 7

Https://entekgroupinc-my.sharepoint.com/personal/gmoralez_entekgroup_com/Documents/Desktop/Center ASB COC/BLK ASB 4-24-24.docx

Delivered by:

Date: Date:

4125124 Time: (0:55 AD)/PM 4,25,24 Time: 10

AM/PM

Received by:



71137

ENTEK CONSULTING GROUP, INC. 4200 ROCKLIN ROAD, SUITE 7 ROCKLIN, CA 95677 (916) 632-6800 PHONE

(916) 632-6812 FAX mainoffice@entekgroup.com

Date of Sampling: 4-24-24 Lab: Asbestech Job Number: 24-7184 Collected by: Gerald Moralez Client Name: Center Joint Unified School District Turnaround Time: 3-Day, Monday, 4-29-24 Site Address: District Office Annex ANALYSIS REQUESTED: Asbestos by PLM 3243 Center Carry in 5767 Greenback Lanewith Dispersion Staining Antelene, OA 95843 Sacramento, CA 95841

Special Instructions: Stop analysis upon first positive result (>1%) for sample in a series. Also stop analysis upon first positive result (>1%) in the joint compound for sample series.

Please e-mail results at mainoffice@entekgroup.com and rmetzen@entekgroup.com as soon as available and include copy of submittal with those results.

SAMPLE #	MATERIAL DESCRIPTION/LOCATION
ECG-24-7184-16B	Black Felt Roofing Paper, Westside, Building 7
ECG-24-7184-17A	Red Terracotta Roofing Shingles, Eastside, Building 7
ECG-24-7184-17B	Red Terracotta Roofing Shingles, Westside, Building 7


Https://entekgroupinc-my.sharepoint.com/personal/gmoralez_entekgroup_com/Documents/Desktop/Center ASB COC/BLK ASB 4-24-24.docx

Delivered by:


Received by:


Date: Date:


 $\frac{4}{25}$, $\frac{24}{25}$ Time: $\frac{10.55}{100}$ ATM,



Page 4 of 4










Center Joint Unified School District District Office Annex 3243 Center Court Lane Antelope, CA 95843 Entek Consulting Group, Inc. 4200 Rocklin Road, Suite 7 Rocklin, CA 95677 Map Not to Scale

Asbestos Bulk Sample Locations Collected by ---Gerald Moralez On Date –April 24, 2024 Project Number 24-7184







AIR QUALITY

Asbestos Survey Form

(See Instructions)

777 12th Street, 3rd Floor Sacramento, CA 95814 Office (916) 874-4800 Fax (916) 874-4899 Email:

asbestos@airquaility.org

1. Purpose of Surve	∋y			Re	novation				Demolitio	on	
2. Facility Informati	on										
Project Area(s) Descriptio	'n										
Address City # of Structures											
3. Owner Information	on										
Name											
Address					City/State				Zip		
Contact	Phone Fax Email										
4. Consultant Inform	nation		Surve	ey Date	(s):		I				
Company Name Entek	Consulti	ng Group,	Inc.	_	<u> </u>						
Name									DOSH #		
Address 4200 Rocklin Road, Su	iite 7				City/State Rocklin, Cali	fornia			Zip 95677		
Phone (916) 632-6800						letzen					
5. Client Information (If different than owner) General Contractor Insurance Company Architect Property Manager Other											
Name											
Address					City/S	State				Zip	95678
Contact		Phone			Fax			Email			
6. Have all of the su	ispect n	naterials	that w	vill be d	isturbed b	een sampled?				∎ Ye ⊐No	
If no, explain why:											
7. Summary of Tota	l Asbes	tos Cont	aining	y Materi	ial (ACM) F	indings					
Regulated Asbestos	Containii	ng Materia	al (RAC	CM)		Catego	ory II		Ca	ateg	ory I
(Includes materials sub damaged materials)	oject to kr	nown mech	nanical	removal	and fire						
Square Ft.	Linear Ft.			Cubic Ft.		Square Ft.	Linear F	₹t.	Square F	t.	Linear Ft.
To rece	eive futur	e SMAQM	ID Rule	e update	es and chan	ges affecting yo	ur industr	y (che	ck one bo	x):	
□ Please send e-mail not	ices to				will sign up m	nyself at <u>www.airqua</u>	ality.org/lists	erve/ to	o receive em	aileo	notices.
I am already subscribe	I am already subscribed.										

SACRAMENTO METROPOLITAN



Asbestos Renovation/Demolition Notification Form

1	Building Department Permit Application # (if known) :		 Renovation (Do not complete Section 5) Demolition (Complete all sections) Ordered Demo - Attach ordered demo letter Emergency Demo - SMAQMD Emergency #: 					
	Contractor		Owner					
	Address		Address					
2	City, State / Zip		Ci	ty, State /	Zip			
-	Email		Fr	nail				
	Telephone		Te	elephone				
2	Structure Name	Renova	atior	n Area				# of Floors
3	Project Address	City / Z	Zip					Year
	Preference for E-mail :				Other :			Built
4	return of form							
	DEMOLITION ONLY – Start date must be at least 10 wo	orking days	<u>s</u> froi	m the day of	your postm	ark ol	^r hand deliver	ry of this form.
			R	evision #	1234	5	6789	(circle)
	Start Date//		New Start Date//					
5	Completion Date/ New Completion Date/					/		
	Method of Demo (Check Applicable): Manual/Hand Tools Mechanical/Heavy Equipment Othe						ent Other	
	Procedure to be followed if RACM is found or Category II material becomes friable:							
	I have read and understand the directions. The information on this form is true and accurate. I certify that the asbestos survey conducted represents the facility as built.							
	Applicant Name (Print)			Owne		Permi	t may be issued o	n:
6	Phone Number			Rep /	•			
Ŭ					actor			
	Applicant's Signature			Date				
	Have DOCH Consultant complete and sign below	D ottoob o	0.000	lated Aches			and Consulta	ntio ronort
	Have DOSH Consultant complete and sign below O	R attach c	omp	ieted Aspes	tos Survey r	-orm a	and Consultai	nt s report.
ΟΝΓΥ	Company Name		Τe	elephone				
	Surveyor Name		DOSH # Survey Date			ate		
USE	Analytical Method	Pt Cou	nt N	laterials <	10%? 🗌 Y	es [] No 🗌 De	clined by Client
				Linear Feet Cubic Feet		t		
CONSULTANT	Amount of Category I Amount of Category I							
Project Address City Zip								
00	Suspect Materials Present? Yes No		Сс	onsultant's	Signature	9	Ruan	Metzen
		SMAQME) USI					\mathcal{O}
	Date Received / Date Postmarked			Date Appro		ned		-
	Project # Check # R	Receipt #		A	mount Paid _		Stat	IT



APPENDIX B

LEAD RELATED DOCUMENTS

- Lead in Paint Samples Analysis Report From Microtest
- Bulk Lead Material Analysis Request Form for Entek
- Lead Bulk Sample Location Drawing
- Lead Hazard Evaluation Report (CDPH 8552)



MicroTest Laboratories, Inc. | AIHA ELPAT #160934 3110 Gold Canal Dr, Ste. A, Rancho Cordova, CA 95670 PH 916.567.9808 | FX 916.404.0302 www.microtestlabsinc.com | service@microtestlabsinc.com ***for office use onlv***

Project ID

L34648-51

CLIENT INFORMATION			SAMPLE	JOB SIT	E INFORMATION
Company	Entek Consulting Group, Inc	Date	Wednesday, April 24, 2024	Sampler	Gerald Moralez & Karl Suarez
Name	Ryan Metzen	Time		Project	Center Joint Unified School District
Address	4200 Rocklin Road, Suite 7			Site	Center District Annex
	Rocklin, CA 95677			Address	3243 Center Court Lane
Phone	916.632.6800	Mior	Tost I above torios		Antelope, CA 95843
Email	mainoffice@entekgroup.com	WIICI	oTest Laboratories	Job #	24-7184
	rmetzen@entekgroup.com		Analytical Report	PO #	

Lead in Paint/Bulk Analysis by Flame AA - EPA METHOD 7420/7000B

Client	Laboratory	Client			Reporting	
Sample ID	Sample ID	Sample Description	Matrix	Results	Limits (RL)	Comments
ECG-24-	L34648	Exterior Blue Paint on Wood, Southside, Building 1	Paint	<rl %="" td="" wt<=""><td>0.01 %Wt</td><td></td></rl>	0.01 %Wt	
7184-01Pb				<rl ppm<="" td=""><td>100 PPM</td><td></td></rl>	100 PPM	
ECG-24-	L34649	Malleable Roof Flashing, Northwest Side, Building 3	Paint	95.75 % Wt	2 %Wt	
7184-02Pb				957468 PPM	20000 PPM	
ECG-24-	L34650	Blue Paint on Metal, Westside, Building 7	Paint	<rl %="" td="" wt<=""><td>0.01 %Wt</td><td></td></rl>	0.01 %Wt	
7184-03Pb				<rl ppm<="" td=""><td>100 PPM</td><td></td></rl>	100 PPM	
ECG-24-	L34651	Malleable Roofing Jack, Westside Building 7	Paint	96.11 % Wt	2 %Wt	
7184-04Pb				961051 PPM	20000 PPM	

Date Received:	Thursday, April 25, 2024
Date Analyzed:	Thursday, April 25, 2024
Date Reported:	Monday, April 29, 2024

Analyst: Erich Bowman

Authorized Signatory:

Kelly Favero - Lab Manager

This report applies to the standards and procedures indicated to the specific samples analyzed. Samples have NOT been corrected for blank values. EPA 3050B Mod.



ENTEK CONSULTING GROUP, INC. 4200 ROCKLIN ROAD, SUITE 7 ROCKLIN, CA 95677 (916) 632-6800 PHONE (916) 632-6812 FAX mainoffice@entekgroup.com

Project ID: L34648-51 Client: Entek Receipt Date: 04/25/24 Count: 4 TAT: 2-Day

Date of Sampling: 4-24-24	Lab: MicroTest
Job Number: 24-7184	Collected by: Gerald Moralez & Karl Suarez
Client Name: Center Joint Unified School District	Turnaround Time: 3-Day, Monday, 4-29-24, End Of Day
Site Address: Center District Annex	ANALYSIS REQUESTED: Lead by Flame
3243 Center Cart a 3234 Center Court Lane	Atomic Absorption Spectroscopy
Antelope, CA 95843 Antelope, CA 95843	

5 -291-24

Special Instructions: Please report result in PPM and % by weight. Please email results as soon as possible.


SAMPLE #	MATERIAL DESCRIPTION/LOCATION		
ECG-24-7184-01Pb	Exterior Blue Paint on Wood, Southside, Building 1		
ECG-24-7184-02Pb	Alleable Roof Flashing, Northwest Side, Building 3		
ECG-24-7184-03Pb	Blue Paint on Metal, Westside, Building 7		
ECG-24-7184-04Pb	Malleable Roofing Jack, Westside Building 7		

Https://entekgroupinc.sharepoint.com/sites/Entekgroup/Shared Documents/Clients/Center JUSD/24-7184 District Annex Roof - AsbPb/Bulk Pb/BLK Pb COC 4-24-24.docx


Delivered by:



<u>4125124</u> Time: <u>10:29</u> AV/PM



Page 1 of 1



04D


Building 1 and 2

01Pb

Center Joint Unified School District District Office Annex 3243 Center Court Lane Antelope, CA 95843 Entek Consulting Group, Inc. 4200 Rocklin Road, Suite 7 Rocklin, CA 95677 Map Not to Scale


Lead Bulk Sample Locations Collected by ---Gerald Moralez On Date –April 24, 2024 Project Number 24-7184 Ψ

N



Center Joint Unified School District District Office Annex 3243 Center Court Lane Antelope, CA 95843 Entek Consulting Group, Inc. 4200 Rocklin Road, Suite 7 Rocklin, CA 95677 Map Not to Scale

Lead Bulk Sample Locations Collected by ---Gerald Moralez On Date –April 24, 2024 Project Number 24-7184



Center Joint Unified School District District Office Annex 3243 Center Court Lane Antelope, CA 95843 Entek Consulting Group, Inc. 4200 Rocklin Road, Suite 7 Rocklin, CA 95677 Map Not to Scale

Lead Bulk Sample Locations Collected by ---Gerald Moralez On Date –April 24, 2024 Project Number 24-7184

LEAD HAZARD EVALUATION REPORT

Section 1 — Date of Lead Hazard Evaluation							
Section 2 — Type of Lead H	lazard Evaluation (Check or	ne box only)					
Lead Inspection Risk assessment Clearance Inspection Other (specify)							
Section 3 — Structure Where Lead Hazard Evaluation Was Conducted							
Address [number, street, apartment (if applicable)]		City	County	Zip Code			
Construction date (year) of structure	Type of structure		Children living in structure?	1			
	Multi-unit building	School or daycare	Yes No				
	Single family dwelling	Other	Don't Know				
Section 4 — Owner of Structure (if business/agency, list contact person)							
Name			Telephone number				
Address [number, street, apartme	ent (if applicable)]	City	State	Zip Code			
Section 5 – Results of Lea	d Hazard Evaluation (check	all that apply)					
No lead-based paint detected Intact lead-based paint detected Deteriorated lead-based paint detected							
No lead hazards detected	Lead-contaminated dust	found Lead-contam	inated soil found Othe	r			
Section 6 – Individual Con	ducting Lead Hazard Evalu	ation					
Name			Telephone number				
Address [number, street, apartme	ent (if applicable)]	City	State	Zip Code			
CDPH certification number Sign		ature Ryan Metze	n	Date			
Name and CDPH certification nu	mber of any other individuals cor	nducting sampling or testing (if applicable)	1			

Section 7 – Attachments

A. A foundation diagram or sketch of the structure indicating the specifc locations of each lead hazard or presence of lead-based paint;

B. Each testing method, device, and sampling procedure used;

C. All data collected, including quality control data, laboratory results, including laboratory name, address, and phone number.

First copy and attachments retained by inspector

Second copy and attachments retained by owner

Third copy only (no attachments) mailed or faxed to:


California Department of Public Health Childhood Lead Poisoning Prevention Branch Reports 850 Marina Bay Parkway, Building P, Third Floor Richmond, CA 94804-6403 Fax: (510) 620-5656



APPENDIX C

BACK UP DOCUMENTS

- Site Map
- Photo Log
- Inspector Accreditations and Certifications
- Laboratory Accreditations for Asbestos and Lead Analysis



Center Joint Unified School District District Office Annex 3243 Center Court Lane Antelope, CA 95843

ጥ


Ν

Entek Consulting Group, Inc. 4200 Rocklin Road, Suite 7 Rocklin, CA 95677 Map Not to Scale

Site Map Project Number 24-7184

Photo Log

Job Number:	24-7184	Date:	4-24-24
Client:	Center Joint Union School District		
Site Address:	3243 Center Court Lane, Antelope, CA 95843		



State of California Division of Occupational Safety and Health Certified Asbestos Consultant

Ryan_Metzen



Certification No. _______ Expires on _______

Expires on 12/13/24 This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code.



Gerald E. Moralez



Certification No. _23-7389

Expires on ____09/22/24

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code.



STATE OF CALIFORNIA DEPARTMENT OF PUBLIC HEALTH



LEAD-RELATED CONSTRUCTION CERTIFICATE

INDIVIDUAL:

CERTIFICATE TYPE:

Lead Inspector/Assessor

NUMBER:

LRC-00007452

EXPIRATION DATE:

9/20/2024



Ryan Metzen

Disclaimer: This document alone should not be relied upon to confirm certification status. Compare the individual's photo and name to another valid form of government issued photo identification. Verify the individual's certification status by searching for Lead-Related Construction Professionals at www.cdph.ca.gov/programs/clppb or calling (800) 597-LEAD



STATE OF CALIFORNIA DEPARTMENT OF PUBLIC HEALTH



LEAD-RELATED CONSTRUCTION CERTIFICATE

CERTIFICATE TYPE:



Lead Sampling Technician

Lead Supervisor

LRC-00005992

NUMBER:

LRC-00010718

EXPIRATION DATE:

12/28/2024

4/10/2024

Gerald Moralez Jr

Disclaimer: This document alone should not be relied upon to confirm certification status. Compare the individual's photo and name to another valid form of government issued photo identification. Verify the individual's certification status by searching for Lead-Related Construction Professionals at www.cdph.ca.gov/programs/clppb or calling (800) 597-LEAD



STATE OF CALIFORNIA DEPARTMENT OF PUBLIC HEALTH

LEAD-RELATED CONSTRUCTION CERTIFICATE

INDIVIDUAL:

CERTIFICATE TYPE:

Lead Inspector/Assessor

Lead Sampling Technician

Karl Suarez

Disclaimer: This document alone should not be relied upon to confirm certification status. Compare the individual's photo and name to another valid form of government issued photo identification. Verify the individual's certification status by searching for Lead-Related Construction Professionals at www.cdph.ca.gov/programs/clppb or calling (800) 597-LEAD

NUMBER:

LRC-00011068

LRC-00008454



EXPIRATION DATE:

4/7/2025

3/25/2024





Certificate of Accreditation to ISO/IEC 17025:2017

NVLAP LAB CODE: 101442-0

ASBESTECH

Rancho Cordova, CA

is accredited by the National Voluntary Laboratory Accreditation Program for specific services, listed on the Scope of Accreditation, for:

Asbestos Fiber Analysis

This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2017. This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality management system (refer to joint ISO-ILAC-IAF Communique dated January 2009).

2023-07-01 through 2024-06-30

Effective Dates



For the National Voluntary Laboratory Accreditation Program



SCOPE OF ACCREDITATION TO ISO/IEC 17025:2017

ASBESTECH

11151 Sun Center Drive, Suite B Rancho Cordova, CA 95670 Mr. Tommy Conlon Phone: 916-481-8902 Fax: 916-481-3975 Email: asbestech@sbcglobal.net http://www.asbestechlab.com

ASBESTOS FIBER ANALYSIS

NVLAP LAB CODE 101442-0

Bulk Asbestos Analysis

CodeDescription18/A03EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials

Airborne Asbestos Analysis

CodeDescription18/A02U.S. EPA's "Interim Transmission Electron Microscopy Analytical Methods-Mandatory and
Nonmandatory-and Mandatory Section to Determine Completion of Response Actions" as found in
40 CFR, Part 763, Subpart E, Appendix A.

For the National Voluntary Laboratory Accreditation Program





CALIFORNIA STATE

ENVIRONMENTAL LABORATORY ACCREDITATION PROGRAM

CERTIFICATE OF ENVIRONMENTAL LABORATORY ACCREDITATION

Is hereby granted to

MicroTest Laboratories, Inc.

3110 Gold Canal Drive

Rancho Cordova, CA 95670

Scope of the certificate is limited to the "Fields of Accreditation" which accompany this Certificate.

Continued accredited status depends on compliance with applicable laws and regulations, proficiency testing studies, and payment of applicable fees.

This Certificate is granted in accordance with provisions of Section 100825, et seq. of the Health and Safety Code.

Certificate No.: 2974

Effective Date: 7/1/2022

Expiration Date: 6/30/2024

Christine Sotelo, Program Manager Environmental Laboratory Accreditation Program

Sacramento, California subject to forfeiture or revocation



CALIFORNIA STATE ENVIRONMENTAL LABORATORY ACCREDITATION PROGRAM Fields of Accreditation



MicroTest Laboratories, Inc.

3110 Gold Canal Drive Rancho Cordova, CA 95670 Phone: 9165679808 Certificate Number: 2974 Expiration Date: 6/30/2024

Field of Accreditation:114 - Inorganic Constituents in Hazardous Waste					
114.345	002	Antimony	EPA 6020 B		
114.345	003	Arsenic	EPA 6020 B		
114.345	004	Barium	EPA 6020 B		
114.345	005	Beryllium	EPA 6020 B		
114.345	006	Cadmium	EPA 6020 B		
114.345	800	Chromium	EPA 6020 B		
114.345	009	Cobalt	EPA 6020 B		
114.345	010	Copper	EPA 6020 B		
114.345	012	Lead	EPA 6020 B		
114.345	016	Nickel	EPA 6020 B		
114.345	018	Selenium	EPA 6020 B		
114.345	021	Thallium	EPA 6020 B		
114.345	023	Zinc	EPA 6020 B		
114.345	024	Molybdenum	EPA 6020 B		
114.515	001	Lead	EPA 7420		
114.545	001	Mercury	EPA 7471 B		
Field of Accreditation:115 - Leaching/Extraction Tests and Physical Characteristics of Hazardous Waste					
115.055	001	Waste Extraction Test (WET)	CCR Chapter11, Article 5, Appendix II		
115.085	001	Toxicity Characteristic Leaching Procedure (TCLP)	EPA 1311		
Field of Accreditation:121 - Bulk Asbestos Analysis of Hazardous Waste					
121.010	001	Bulk Asbestos	EPA 600/M4-82-020		
-					