Antelope View Charter School

RECORD OF FRIABLE AND NON-FRIABLE ACM (FORM B)

THREE-YEAR REINSPECTION

							CODE 73973-6032	916	
	DL LOPE VIEW CHARTER SCHOOL - NO LONGE FACILITY IS NOW GENERAL DISTRICT OFF		RATIO	N AS OF	JULY		100l phone 5) 338-6450		
ADDRE 8300 \	ESS (NUMBER) (STREET Vatt Avenue)		(CITY) Antelope	e, CA		(ZIP) 95843		
	Each building and functional space with friable completion of <u>FORM C</u> (PHYSICAL AND HAZ ACBM). Indicate location of material on bluep copy (Sec. 763.93).	ARD ASSE	friable a SSMEI	assumed NT OF FF	RIABLE A	ACBN	A OR FRIAE	BLE ASSUM	ED
		CHE		NE			CHEC	K ONE	
LINE	BUILDING NAME & FUNCTIONAL SPACE	SUR-				ACE	BM	ASSUME	D ACBM
	(Indicate Address if Different From Above)	FACING	TSI	MISC	FRIABI	E	NON- FRIABLE	FRIABLE	NON- FRIABLE
1.	UNIT A (MPR)	х		Х			х		х
2.	UNITS B & C	х		Х					Х
3.	UNIT D (ADMINISTRATION & ROOM 47)			Х					Х
4.	UNIT E (PORTABLE CLASSROOMS 22-24)			Х					х
5.	UNIT F (CLASSROOMS 2, 3, & RESTROOMS)			Х					х
6.	UNIT G (PORTABLE CLASSROOMS 19-21)			Х					х
7.	COMPUTER LAB (FKA: UNIT H - NEW BUILDING) DISTRICT MUST CERTIFY								
8.	UNIT J1 - CLASSROOM 4	х							х
9.									
10.									
11.									
12.									
13.									
14.									
15. C:\Users\se	lbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Cer	nter USD\20-555	1 3 Yr Reir	spections\Sit	es\Antelope \	/iew C	harter School\AV(C Form B wod	

See attached "Homogeneous Materials Records" for all materials and their locations by building. On Form B all buildings are listed, and a summary of all non-friable and friable material is provided. Friable materials and their locations are listed separately under each building on Form B.

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Unit A (MPR)

District: Center Unified School District

School: Antelope View Charter School (No Longer Operating as of July 2017)

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Conditic	on: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	1	NONE DETECTED	600 S	LOCKER ROOM, MECHANICAL ROOM, AND ABOVE COACHES RESTROOM	(13)	REPRESENTED BY SAMPLES HMS-CJHS-S23- 01A-E COLLECTED ON 5-1-92.	Ν
М	12" CEILING TILE (FISSURE PATTERN)	4	NONE DETECTED	4,325 S	MPR & BOILER ROOM	(13)	REPRESENTED BY SAMPLES HMS-CJHS-S23- 04A-C COLLECTED ON 5-1-92.	Ν
М	SHEET VINYL FLOORING (GRAY/WHITE)	8	NONE DETECTED	900 S	KITCHEN	(13)	SAMPLES HMS-CJHS-S23-08A-C COLLECTED ON 5-1-92.	N
S	PLASTER	9	TRACE	5,000 S	BOY'S & GIRL'S RESTROOMS, P.E. STORAGE, LOCKER ROOMS AND KITCHEN	(1) (4)		N
М	12" VINYL FLOOR TILE (DARK BLUE) & MASTIC	20	ASSUMED POSITIVE	800 S	MPR	(1) (4)		Ν
м	12" VINYL FLOOR TILE (OFF WHITE) & MASTIC	126	NONE DETECTED	400 S	STORAGE/WATER HEATER	(13)		Ν
М	12" VINYL FLOOR TILE (LIGHT BLUE) & MASTIC	142	ASSUMED POSITIVE	1,200 S	MPR	(1) (4)		Ν
М	6" COVE BASE (CREAM) ADHESIVE	143	ASSUMED POSITIVE	200 L	MPR	(1) (4)		Ν
S	WALL TEXTURE (KNOCKDOWN STYLE)	147	ASSUMED POSITIVE	400 S	STORAGE/WATER HEATER AND CUSTODIAL ROOM AT GIRLS RESTROOM	(1) (4)		Ν
М	SHEET VINYL FLOORING - BLUE/WHITE	165	ASSUMED POSITIVE	100 S		(1)		Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Antelope View Charter School\AVC HMR.wpd
CONDITION CODE

General Condition:
Change in Condition:(1) Good(2) Damaged(3) Significantly Damaged(25% or more)Abated:
Miscellaneous:(4) No(5) Yes (If Yes, explain under comments)(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & RestrictedMiscellaneous:(11) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected

District: Center Unified School District

Inspector: Matt Reilly

Date of Inspection: November 6, 2020

Building: Units B & C

School: Antelope View Charter School (No Longer Operating as of July 2017)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition	: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	1	NONE DETECTED	6,100 S	MUSIC ROOM, CLASSROOM 45, AND ARTS & CRAFTS		SAMPLE HMS-CJHS-S23-01E COLLECTED ON 5-1-92.	Ν
М	12" CEILING TILE (FISSURE PATTERN)	4	NONE DETECTED	1,600 S	MUSIC ROOM AND CLASSROOM 45		REPRESENTED BY SAMPLES HMS-CJHS-S23- 04A-C COLLECTED ON 5-1-92.	Ν
М	12" VINYL FLOOR TILE (OFF-WHITE) & MASTIC	7	NONE DETECTED	2,700 S	MUSIC ROOM, CLASSROOM 45, AND ARTS & CRAFTS		REPRESENTED BY SAMPLE HMS-CJHS-07A COLLECTED ON 5-1-92.	Ν
М	12" VINYL FLOOR TILE (BLUE) & MASTIC	10	NONE DETECTED	300 S	MUSIC ROOM		SAMPLE HMS-CJHS-S23-10A COLLECTED ON 5-1-92.	Ν
Μ	4" COVE BASE (BLACK) ADHESIVE	127	ASSUMED POSITIVE	200 L	CLASSROOM 44	(1) (4)		Ν
Μ	2' X 4' CEILING PANELS (FISSURE PATTERN)	144	ASSUMED POSITIVE	960 S	ARTS & CRAFTS ROOM (MIDDLE ROOM)		WATER STRAN IN STORAGE OF CRAFT ROOM.	Ν
S	WALL TEXTURE (ORANGE PEEL STYLE)	145	ASSUMED POSITIVE	2,000 S	CLASSROOMS 44 & 45	(1) (4)		Ν
S	WALL/CEILING TEXTURE (KNOCKDOWN)	147	ASSUMED POSITIVE	200 S	ROOM 45A AT STORAGE	(1) (4)		Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Antelope View Charter School\AVC HMR.wpd

General Condition: Change in Condition: Abated: Miscellaneous:

(1) Good
(2) Damaged
(3) Significantly Damaged (25% or more)
(4) No
(5) Yes (If Yes, explain under comments)
(6) Repaired
(7) Removed
(8) Encapsulated
(9) Enclosed
(11) Inaccessible, no inspection data
(12) Other (Explain under comments)

osulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: November 6, 2020

District: Center Unified School District

Inspector: Matt Reilly Building: Unit D (Administration)

School: Antelope View Charter School (No Longer Operating as of July 2017)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	n: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	1	NONE DETECTED	9,000 S	ADMINISTRATION	(13)	SAMPLE HMS-CJHS-S23-01A COLLECTED ON 5-1-92.	Ν
М	SHEET VINYL FLOORING (ORANGE)	2	NONE DETECTED	200 S	ADMINISTRATION & RESTROOM	(13)	SAMPLE HMS-CJHS-S23-02A COLLECTED ON 5-1-92.	N
М	12" VINYL FLOOR TILE (OLIVE) & MASTIC	3	NONE DETECTED	600 S	ADMINISTRATION & COPY ROOM	(13)	SAMPLE HMS-CJHS-S23-03A COLLECTED ON 5-1-92.	N
М	12" CEILING TILE	4	NONE DETECTED	900 S	LIBRARY	(13)	SAMPLES HMS-CJHS-S23-04A-C COLLECTED ON 5- 1-92.	Ν
S	WALL/CEILING TEXTURE (ORANGE PEEL STYLE)	149	ASSUMED POSITIVE	4,000S	ADMINISTRATION	(1) (4)		Ν
М	COVE BASE ADHESIVE	160	ASSUMED POSITIVE	500 L	ADMINISTRATION	(1) (4)		Ν
М	CARPET ADHESIVE	161	ASSUMED POSITIVE	3,000 S	THROUGHOUT	(1) (4)		Ν
М	2' X4' CEILING PANELS (FISSURE PATTERN)	162	ASSUMED POSITIVE	3,000 S	ADMINISTRATION	(1) (4)		Y

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Antelope View Charter School\AVC HMR.wpd

CONDITION CODE

<u>General Condition:</u> Change in Condition:

(1) Good (4) No

Abated: Miscellaneous:

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7) (6) Repaired

psulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

District: Center Unified School District

Building: Unit E (Portable Classrooms 22-24)

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	on: Code & Comments	Friable Yes/No
М	DRYWALL	99	ASSUMED POSITIVE	6,000 S	CLASSROOMS 22-24	(11)	DRYWALL IS ASSUMED POSITIVE TO EXIST BEHIND ALL WALL SURFACES.	Ν
М	12" VINYL FLOOR TILE (LIGHT BROWN) & MASTIC	129	ASSUMED POSITIVE	36 S	CLASSROOM 24	(11)	CARPET OVER THE TILE	N
М	4" COVE BASE (BLUE) ADHESIVE	153	ASSUMED POSITIVE	360 L	CLASSROOMS 22-24	(1) (4)		Ν
М	2' X 4' CEILING PANELS	N/A	NOT SUSPECT	1,800 S	CLASSROOMS 22-& 23	(13)	VINYL COATED FIBERGLASS PANELS	Y
М	CARPET ADHESIVE	161	ASSUMED POSITIVE	1,800 S	CLASSROOMS 22 & 23	(1) (4)		N
					C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Docu CONDITION CODE	ments\Clients	s\Center USD\20-5551 3 Yr Reinspections\Sites\Antelope View Charter Scho	ol\AVC HMR.wpd

General Condition: Change in Condition:

Abated:

(1) Good

(4) No (6) Repaired

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (1) (9) Enclosed (10) Isolated & Restricted

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected Miscellaneous:

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

District: Center Unified School District

Building: Unit F (Classrooms 2, 3, & Restrooms)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	1	NONE DETECTED	2,100 S	CLASSROOMS 2 & 3, RESTROOMS AND CUSTODIAL OFFICE	(13) SAMPLE HMS-CJHS-S23-01B COLLECTED ON 5-1-92.	N
S	WALL TEXTURE (ORANGE PEEL STYLE)	149	ASSUMED POSITIVE	UNDETERMINED	CLASSROOM 2	(1) (4)	N
М	12" VINYL FLOOR TILE (LIGHT BLUE) & MASTIC	151	ASSUMED POSITIVE	450 S	CLASSROOM 3	(1) (4)	Ν
М	12" VINYL FLOOR TILE (LIGHT GRAY) & MASTIC	152	ASSUMED POSITIVE	550 S	CLASSROOM 3, STORAGE ROOM AND WATER HEATER CLOSET, ROOM 2 AT KITCHENETTE	(1) (4)	Ν
М	2' X 4' CEILING PANELS (FISSURE PATTERN)	154	ASSUMED POSITIVE	1,500 S	CLASSROOMS 2 & 3	(1)	Y
М	4" COVE BASE (BLUE) ADHESIVE	153	ASSUMED POSITIVE	200 L	CLASSROOMS 2 & 3, STORAGE ROOM AND WATER HEATER CLOSET	(1) (4)	N
М	CARPET ADHESIVE	161	ASSUMED POSITIVE	900 S	CLASSROOM 2	(1) (4)	N
М	12" CEILING TILE (FISSURE PATTERN)	163	ASSUMED POSITIVE	900 S	CLASSROOM 2	(1) (4)	N
S	EXTERIOR STUCCO	164	ASSUMED POSITIVE	1,000 S	COVERED WALKWAY	(1) (4)	N

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Antelope View Charter School\AVC HMR.wpd CONDITION CODE

General Condition:

(1) Good (4) No

School: Antelope View Charter School (No Longer Operating as of July 2017)

Change in Condition: Abated:

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (1)

psulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

(6) Repaired Miscellaneous:

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

District: Center Unified School District

Building: Unit G (Portable Classrooms 19-21)

School: Antelope View Charter School (No Longer Operating as of July 2017)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
Μ	DRYWALL	99	ASSUMED POSITIVE	2,100 S	CLASSROOMS 19-21	(11) DRYWALL IS ASSUMED TO EXIST BEHIND ALL WALL SURFACES.	N
Μ	4" COVE BASE (BROWN) ADHESIVE	130	ASSUMED POSITIVE	240 L	CLASSROOMS 20 & 21	(1) (4)	N
Μ	4" COVE BASE (GRAY) ADHESIVE	146	ASSUMED POSITIVE	120 L	CLASSROOM 19	(1) (4)	N
Μ	2' X 4' CEILING PANELS	N/A	NOT SUSPECT	2,700 S	CLASSROOMS 19-21	(13) VINYL COATED FIBERGLASS PANELS	N
Μ	CARPET ADHESIVE	161	ASSUMED POSITIVE	2,700 S	CLASSROOMS 19-21	(1) (4)	N

CONDITION CODE

General Condition: Change in Condition:

Abated:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7) (4) No (6) Repaired

osulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected Miscellaneous: (11) Inaccessible, no inspection data

District: Center Unified School District

School: Antelope View Charter School (No Longer Operating as of July 2017)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	n: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	1	NONE DETECTED	2,500 S	CLASSROOM 4	(13)	SAMPLE HMS-CJHS-S23-01C COLLECTED ON 5-1-92.	Ν
м	12" CEILING TILE (FISSURE PATTERN)	4	NONE DETECTED	1,212 S	CLASSROOM 4	(13)	REPRESENTED BY SAMPLES HMS-CJHS- C23-04A-C COLLECTED ON 5-1-92.	Ν
М	12" VINYL FLOOR TILE GRAY/WHITE) & MASTIC	5	NONE DETECTED	1,212 S	CLASSROOM 4	(13)	SAMPLE HMS-CJHS-S23-05A COLLECTED ON 5-1-92.	Ν
S	TEXTURE (KNOCKDOWN STYLE)	147	ASSUMED POSITIVE	1,000 S	CLASSROOM 4	(1) (4)		Ν
М	COVE BASE ADHESIVE	160	ASSUMED POSITIVE	150 L	THROUGHOUT	(1) (4)		Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Antelope View Charter School\AVC HMR.wpd

CONDITION CODE

General Condition: Change in Condition:

Abated:

(1) Good

(4) No (6) Repaired Miscellaneous:

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7)


(9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection: November 6, 2020

Inspector: Matt Reilly


Building: Unit J1 (Classroom 4)



Center Unified School District General District Offices – FKA: Antelope View Charter 8300 Watt Avenue Antelope, CA 95843 Entek Consulting Group, Inc. 4200 Rocklin Road, Suite 7 Rocklin, CA 95677 Map Not to Scale

Three-Year AHERA Reinspection Conducted by Matt Reilly On November 6, 2020 Project Number 20-5551

Cloud\ Clients\Center USD\20-5551 3 Yr Reinspections\Sites\AVC



RECORD OF FRIABLE AND NON-FRIABLE ACM (FORM B)

Inspection Date November 6, 2020

		THRE	E-YEAR F	REINSI	PECTIO	N				
								S CODE 73973-3430	378	
SCHOC Center)L High School							HOOL PHONE 6) 338-6420		
ADDRE 8306 V	SS Vatt Avenue	(NUMBER) (STREET	Γ)		(CITY) Antelope	, CA		(ZIP) 95843		
	completion of FOI	functional space with friable <u>RM C</u> (PHYSICAL AND HAZ location of material on bluep 3).	ARD ASSE	riable a	ssumed ANT OF FF	RIABLE	ACB	M OR FRIAE	BLÉ ASSUM	ED
			СН	ECK O	NE			CHEC	K ONE	
LINE	BUILDING NAM	E & FUNCTIONAL SPACE	SUR-				AC	BM	ASSUME	D ACBM
	(Indicate Address if I	Different From Above)	FACING	TSI	MISC	FRIAB	BLE	NON- FRIABLE	FRIABLE	NON- FRIABLE
1.	BAND	DISTRICT MUST CERTIFY								
2.	C TRAIN CONTAII	NERS - (7) NO SUSPECT ACBM								
3.	CLASSROOMS 20	0-207 & TL DISTRICT MUST CERTIFY								
4.	CLASSROOMS 40	0-407 & CCC LAB DISTRICT MUST CERTIFY								
5.	CLASSROOMS 70	00-703 DISTRICT MUST CERTIFY								
6.	LIBRARY BUILDIN									
7.	THEATER	DISTRICT MUST CERTIFY								
8.	PORTABLES 208-	212 DISTRICT MUST CERTIFY								
9.	PORTABLES 300-	306 DISTRICT MUST CERTIFY								
10.	PORTABLES 800-	806 DISTRICT MUST CERTIFY								
11.	PORTABLES 900-	904 DISTRICT MUST CERTIFY								
12.	PORTABLES 905-	907 DISTRICT MUST CERTIFY								
13.	UNIT A - GYM				Х					х
14.	UNIT B - MPR	NO ACBM								
15.	UNIT C - ADMINIS	TRATION & COUNSELING NO ACBM								
16.	UNIT D - RESTRC INACCESSIBLE	OMS - ATTIC								

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Center HS\Center Form B.wpd See attached "Homogeneous Materials Records" for all materials and their locations by building. On Form B all buildings are listed, and a summary of all non-friable and friable material is provided. Friable materials and their locations are listed separately under each building on Form B.

RECORD OF FRIABLE AND NON-FRIABLE ACM (FORM B)

			THRE	E-YEAR F	REINSI	PECTIO	N _				
									S CODE 73973-34303	378	
SCHO Center	OL High School								HOOL PHON 6) 338-6420	NE NUMBEF	2
ADDRI 8306 V	ESS (Vatt Avenue	NUMBER)	(STREE	Г)		(CITY) Antelope	, CA		(ZIP) 95843		
	Each building and fu completion of <u>FORM</u> ACBM). Indicate loc copy (Sec. 763.93).	I C (PHYSICAL	AND HAZ	ARD ASSE	riable a SSMEI	ssumed ANT OF FF	RIABLE	ACB	M OR FRIAE	BLĖ ASSUM	ED
				CH	IECK ON	E			CHECI	K ONE	
LINE	BUILDING NAME & FUN	ICTIONAL SPACE		SUR-				AC	BM	ASSUME	D ACBM
	(Indicate Address if Diffe	erent From Above)		FACING	TSI	MISC	FRIAB	LE	NON- FRIABLE	FRIABLE	NON- FRIABLE
17.	UNIT E - CLASSROO	MS 600-604	NO ACBM								
18.	UNIT F - SHOP CLAS ATTIC INACCESSIBL		NO ACBM								
19.	UNIT G - CLASSROC DIST	OMS 500-504 RICT CLAIMS E	XEMPTION								
20.	UNIT J-2 (CLASSRO	OM 5) DEI	MOLISHED	х		х					Х
21.	UNIT K - WEIGHT RO		OM 807) ECT ACBM								
22.	UNIT N - CLASSROC DISTE	MS 101-109 RICT CLAIMS E	XEMPTION								
23.	UNIT P - (CLASSROO DISTR	OM 6) RICT CLAIMS E	XEMPTION								
24.	UNIT Q - (CLASSRO	OMS 7-10) DEI	MOLISHED	Х		Х					Х
25.		DISTRICT MUS									
	C:\	Users\selbert\Entek C	onsulting Group,	Inc\Entekgroup	 Documer 	its\Clients\Cer	nter USD\20	-5551 3	Yr Reinspections	Sites/Center HS/C	enter Form B.wpd

See attached "Homogeneous Materials Records" for all materials and their locations by building. On Form B all buildings are listed, and a summary of all non-friable and friable material is provided. Friable materials and their locations are listed separately under each building on Form B.

District: Center Unified School District

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Unit A - Gym

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	1	NONE DETECTED	6,000 S	LOBBY, GYM, RESTROOMS, GIRL'S & BOY'S LOCKER ROOMS, COACHES OFFICE, SNACK BAR, TRAINING ROOM, BOILER ROOM, EQUIPMENT ROOM, JANITOR CLOSET, LAUNDRY ROOM, EQUIPMENT NEXT TO GIRL'S COACHING OFFICES, AND CORRIDORS	(13)	Ν
М	12" ACOUSTIC CEILING TILE	2	NONE DETECTED	11,833 S	LOBBY, GYM, AND CORRIDORS	(13)	Ν
М	LINOLEUM (PURPLE)	4	NONE DETECTED	150 S	GYM	(13)	Ν
S	PLASTER	6	NONE DETECTED	15,000 S	LOCKER ROOM & WALLS ADJOINING COACHES OFFICE, TRAINING ROOM, JANITOR CLOSET, AND BOILER ROOM	(13)	Ν
м	LAMINATE WOOD FLOORING	200	NONE DETECTED	1,660 S	LOBBY, SNACK BAR, AND CORRIDORS	(1)	Ν
М	LINOLEUM (RED)	50	ASSUMED POSITIVE	325 S	MEN'S LOBBY RESTROOM	(1) (4)	Ν
М	LINOLEUM (PURPLE/RED)	51	ASSUMED POSITIVE	325 S	WOMEN'S LOBBY RESTROOM	(1) (4)	Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Center HS\Center HMR.wpd
CONDITION CODE

General Condition:
Change in Condition:(1) Good(2) Damaged(3) Significantly Damaged(25% or more)Abated:
Miscellaneous:(4) No(5) Yes (If Yes, explain under comments)(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & RestrictedMiscellaneous:
(11) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

School: Center High School

District: Center Unified School District

School: Center High School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Unit B - MPR

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	1	NONE DETECTED	10,000 S	BOY'S & GIRL'S RESTROOMS, JANITORS ROOM, MPR, SUBFLOOR, KITCHEN RESTROOM, STAGE LIGHTING CONTROL ROOM, KITCHEN DRY STORAGE ROOM, AND MUSIC ROOM	(13)	Ν
М	12" ACOUSTIC CEILING TILE	2	NONE DETECTED	5,950 S	MPR, STAGE, AND MUSIC ROOM	(13)	N
М	LINOLEUM (PURPLE)	4	NONE DETECTED	150 S	GIRL'S RESTROOM	(13)	N
М	LINOLEUM	5	NONE DETECTED	1,550 S	KITCHEN	(13)	N
S	PLASTER	6	NONE DETECTED	4,500 S	KITCHEN	(13)	N
М	LINOLEUM (BLUE/TAN)	7	NONE DETECTED	5,986 S	MPR AND MUSIC ROOM	(13)	N
М	LINOLEUM (BLUE)	8	NONE DETECTED	186 S	BOY'S RESTROOM, STAGE, AND KITCHEN	(13)	Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Center HS\Center HMR.wpd CONDITION CODE

General Condition: Change in Condition:

Abated:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (1) (4) No (6) Repaired

apsulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data Miscellaneous:

District: Center Unified School District

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

School: Center High School

Building: Unit C - Administration & Counseling

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	1	NONE DETECTED	7,000 S	ADMINISTRATION AND COUNSELING	(13)	Ν
М	12" ACOUSTIC CEILING TILE	2	NONE DETECTED	6,525 S	ADMINISTRATION AND COUNSELING	(13)	Ν
М	12" VINYL FLOOR TILE	3	NONE DETECTED	500 S	ADMINISTRATION AND COUNSELING	(13) COVERED WITH CARPET.	Ν
М	LINOLEUM (PURPLE)	4	NONE DETECTED	150 S	ADMINISTRATION	(13)	Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Center HS\Center HMR.wpd CONDITION CODE

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7) General Condition: (1) Good (4) No (6) Repaired Change in Condition: Abated: (9) Enclosed (10) Isolated & Restricted Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Center Unified School District

School: Center High School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Unit D - Restrooms

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No	
Μ	DRYWALL & JOINT COMPOUND	1	NONE DETECTED	3,400 S	BOY'S & GIRL'S RESTROOMS AND JANITORS CLOSET	(13)	Ν	
М	LINOLEUM (PURPLE)	4	NONE DETECTED	400 S	GIRL'S RESTROOM	(13)	Ν	
C:\Users\selbert\	\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Center HMR.wpd CONDITION CODE							
General C	ondition (1) Good	(2) Dama	aged (3)	Significantly Damaged (25% or more)			

Change in Condition: Change in Condition: Abated: Miscellaneous:

(1) Good
(2) Damaged
(3) Significantly Damaged (25% or more)
(4) No
(5) Yes (If Yes, explain under comments)
(6) Repaired
(7) Removed
(8) Encapsulated
(9) Enclosed
(10) Isolated & Restricted
(11) Inaccessible, no inspection data
(12) Other (Explain under comments)
(13) Non-Asbestos/Not Inspected

District: Center Unified School District

School: Center High School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Unit E - Classrooms 600-604

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	1	NONE DETECTED	15,000 S	HOME ECONOMICS, SCIENCE, AND ARTS/CRAFTS	(13)	Ν
М	12" ACOUSTIC CEILING TILE	2	NONE DETECTED	6,093 S	HOME ECONOMICS, SCIENCE, AND ARTS/CRAFTS	(13)	Ν
М	12" VINYL FLOOR TILE	3	NONE DETECTED	1,500 S	ARTS/CRAFTS	(13)	Ν
М	LINOLEUM	14	NONE DETECTED	950 S	HOME ECONOMICS	(13)	Ν
М	12" VINYL FLOOR TILE (TAN)	15	NONE DETECTED	2,940 S	SCIENCE	(13)	Ν
::\Users\selbert\l	I (TAN) I I I I I Isers\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Center HS\Center HMR.wpd CONDITION CODE						

General Condition:	(1) Good	(2)	Damaged	(3)	Significantly Damaged (25% or more)		
Change in Condition:	(4) No	(5)	Yes (If Yes,	expl	ain under comments)		
Abated:	(6) Repaired	(7)	Removed	(8)	Encapsulated (9) Enclosed (1	10) Isolat	ted & Restricted
Miscellaneous:	(11) Inaccessibl	le, no	o inspection of	data	(12) Other (Explain under com	ments)	(13) Non-Asbestos/Not Inspected

District: Center Unified School District

School: Center High School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Unit F - Shop Classrooms

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	1	NONE DETECTED	20,000 S	SHOP	(13)	Ν
М	12" ACOUSTIC CEILING TILE	2	NONE DETECTED	200 S	SHOP	(13)	Ν
М	LINOLEUM (YELLOW & ORANGE)	5	NONE DETECTED	200 S	SHOP	(13)	Ν

\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\S CONDITION CODE

General Condition: Change in Condition: Abated: Miscellaneous:

(1) Good
(2) Damaged
(3) Significantly Damaged (25% or more)
(4) No
(5) Yes (If Yes, explain under comments)
(6) Repaired
(7) Removed
(8) Encapsulated
(9) Enclosed
(11) Inaccessible, no inspection data
(12) Other (Explain under comments) apsulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Center Unified School District

Date of Inspection: November 6, 2020

Building: Unit J2 (Classroom 5)

Inspector: Matt Reilly

School: Center High School (Reassigned from Antelope View Charter School, FKA: Center Jr. High Site)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	1	NONE DETECTED	2,500 S	CLASSROOM 5	(7) BUILDING DEMOLISHED	Ν
М	12" VINYL FLOOR TILE (GRAY/WHITE) & MASTIC	5	NONE DETECTED	600 S	CLASSROOM 5	(7) BUILDING DEMOLISHED	Ν
S	TEXTURE (ORANGE PEEL STYLE)	148	ASSUMED POSITIVE	2,200 S	CLASSROOM 5	(7) BUILDING DEMOLISHED	Ν
М	COVE BASE ADHESIVE	160	ASSUMED POSITIVE	120 L	THROUGHOUT	(7) BUILDING DEMOLISHED	Ν
М	CARPET ADHESIVE	161	ASSUMED POSITIVE	300 S	THROUGHOUT	(7) BUILDING DEMOLISHED	Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Center HS\Center HMR.wpd

CONDITION CODE

General Condition: Change in Condition: Abated: Miscellaneous:

(1) Good

(4) No

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7) (6) Repaired (9) Enclosed (10) Isolated & Restricted

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

District: Center Unified School District

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

School: Center High School (Reassigned from Antelope View Charter School, FKA: Center Jr. High Site)

Building: Unit Q (Science Rooms 8-10)

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
Μ	DRYWALL & JOINT COMPOUND	125	ASSUMED POSITIVE	8,000 S	CLASSROOMS 8-10	(7) BUILDING DEMOLISHED	Ν
Μ	12" VINYL FLOOR TILE (WHITE/GRAY) & MASTIC	133	ASSUMED POSITIVE	2,640 S	CLASSROOMS 8-10	(7) BUILDING DEMOLISHED	N
М	4" COVE BASE (BROWN) ADHESIVE	134	ASSUMED POSITIVE	360 L	CLASSROOMS 8-10	(7) BUILDING DEMOLISHED	Ν
Μ	2' X 4' CEILING PANELS (FISSURE PATTERN)	135	ASSUMED POSITIVE	2,640 S	CLASSROOMS 8-10	(7) BUILDING DEMOLISHED	N
S	TEXTURE (ORANGE PEEL STYLE)	149	ASSUMED POSITIVE	1,500 S	CLASSROOMS 8-10	(7) BUILDING DEMOLISHED	Ν

CONDITION CODE

General Condition: Change in Condition:

(1) Good


Abated:

Miscellaneous:

(2) Damaged (3) Significantly Damaged (25% or more)(5) Yes (If Yes, explain under comments) (4) No

(9) Enclosed (10) Isolated & Restricted

(6) Repaired (7) Removed (8) Encapsulated (11) Inaccessible, no inspection data (12) Oth (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected




Mr They

Center Unified School District Center High School 8306 Watt Avenue Antelope, CA 95843 Entek Consulting Group, Inc. 4200 Rocklin Road, Suite 7 Rocklin, CA 95677 Map Not to Scale

Three-Year AHERA Reinspection Conducted by Matt Reilly On November 6, 2020 Project Number 20-5551

Cloud\ Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Center HS




Antelope, CA 95843

Map Not to Scale

On November 6, 2020 Project Number 20-5551

Cloud\ Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Center HS



RECORD OF FRIABLE AND NON-FRIABLE ACM (FORM B)

		THREE-YEAR	REINSPECTION		
				CDS CODE 34-73973-0000000	
SCHOOL District Facilities				SCHOOL PHONE NUMBER (916) 338-6400	
ADDRESS 8408 Watt Avenue	(NUMBER)	(STREET)	(CITY) Antelope, CA	(ZIP) 95843	

-IMPORTANT-

Each building and functional space with friable ACBM or friable assumed ACBM listed on this form requires completion of <u>FORM C</u> (PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE ACBM OR FRIABLE ASSUMED ACBM). Indicate location of material on blueprint, diagram or narrative in square or linear feet, and attach a copy (Sec. 763.93).

		СН	ECK OI	NE		CHEC	K ONE	
LINE	BUILDING NAME & FUNCTIONAL SPACE	SUR-			AC	BM	ASSUME	D ACBM
	(Indicate Address if Different From Above)	FACING	TSI	MISC	FRIABLE	NON- FRIABLE	FRIABLE	NON- FRIABLE
1.	UNIT A - ADMINISTRATION	х		Х		х		Х
2.	UNIT B - MAINTENANCE	х		Х		х		Х
3.	UNITS C & D - WAREHOUSE	х		Х				Х
4.	UNIT E - TRANSPORTATION			Х				Х
5.	UNIT F - M.O.T.	х		Х				х
6.	UNIT G - C.S.S	х		Х				х
7.	UNIT H - RESTROOMS	х		Х				х
8.	UNIT I - PERSONNEL OFFICE			Х				х
9.	UNIT J - PERSONNEL OFFICE			Х				х
10.	UNIT K - SPECIAL EDUCATION	х		Х				х
11.	UNIT L - NUTRITIONAL SERVICES			Х				х
12.	UNIT M - CONFERENCE ROOM			Х				Х
13.	UNIT N - CONFERENCE ROOM			Х				Х
14.	UNIT O - INSTRUCTIONAL SERVICES			Х				Х
15.								
16.								
17.	port/Entek Conculting Group, Inc/Entekgroup, Documents/Clients/Car							

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\District Office\District Office Form B.wpd

See attached "Homogeneous Materials Records" for all materials and their locations by building. On Form B all buildings are listed, and a summary of all non-friable and friable material is provided. Friable materials and their locations are listed separately under each building on Form B.

District: Center Unified School District

School: District Facility (North)

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Unit A (Administration)

NYL G (TAN) FLOOR TE) & & JOINT ND	4 5 6	10% 2% NONE DETECTED	300 S 64 S	MEN'S & WOMEN'S RESTROOMS TELEPHONE ROOM	(1) (4)(1) (4)	N N
KE) &		NONE		TELEPHONE ROOM	(1) (4)	N
ND	6		F F 00 0			
AM TAPE			5,520 S	MAIN, OFFICES 1-6, KITCHEN, CLOSETS 1 & 2, WOMEN'S & MEN'S RESTROOMS, BUSINESS 1 & 2, PAPER STORAGE, HALLS 1 & 2, AND TELEPHONE ROOM	(13) SAMPLES HMS-DO-S23-06A-C COLLECTED ON 5-7-92.	Ν
	7	NONE DETECTED	80 L	FURNACE ROOM	(13)	Ν
LING SSURE)	107	ASSUMED POSITIVE	240 S	OFFICE 3	(1) (4) FIBERGLASS	Ν
ASE UE) E	111	ASSUMED POSITIVE	50 L	KITCHEN	(1) (4)	N
NYL G (WHITE)	112	ASSUMED POSITIVE	150 S	KITCHEN	(1) (4)	Ν
	113	ASSUMED POSITIVE	80 S	PAPER STORAGE	(1) (4)	Ν
		(WHITE) YL 113	(WHITE) POSITIVE YL 113 ASSUMED POSITIVE	(WHITE)POSITIVEYL113ASSUMED POSITIVE80 S	POSITIVE YL 113 ASSUMED POSITIVE 80 S E) C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Do	(WHITE) POSITIVE 80 S YL 113 ASSUMED POSITIVE 80 S PAPER STORAGE (1) (4)

General Condition: Change in Condition: Abated: Miscellaneous:

(1) Good

(4) No

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)

(6) Repaired

(7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Center Unified School District

School: District Facility (North)

Building: Unit A, Administration

Co	ntin	ued)
-		

Inspector: Matt Reilly

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	6" COVE BASE (GRAY) AHDESIVE	114	ASSUMED POSITIVE	140 L	PAPER STORAGE	(1) (4)	Ν
м	12" VINYL FLOOR TILE (LIGHT BLUE) & MASTIC	115	ASSUMED POSITIVE	50 S	TELEPHONE EQUIPMENT ROOM	(1) (4)	Ν
М	4" COVE BASE (BLACK) ADHESIVE	116	ASSUMED POSITIVE	30 L	TELEPHONE EQUIPMENT ROOM	(1) (4)	N
S	DRYWALL TEXTURE (KNOCKDOWN STYLE)	138	ASSUMED POSITIVE	5,520 S	MAIN, OFFICES 1-6, KITCHEN, CLOSETS 1 & 2, WOMEN'S & MEN'S RESTROOMS, BUSINESS 1 & 2, PAPER STORAGE, HALLS 1 & 2, AND TELEPHONE ROOM	(1) (4)	N
М	4" COVE BASE (BLUE) ADHESIVE	145	ASSUMED POSITIVE	200 L	MAIN, OFFICES 1-6, CLOSETS 1 & 2, BUSINESS 1 & 2, AND HALLS 1 & 2	(1) (4)	N
м	CARPET ADHESIVE	150	ASSUMED POSITIVE	1,500 S	VARIOUS LOCATIONS THROUGHOUT	(1) (4)	N

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\District Office\District Office HMR.wpd

CONDITION CODE

General Condition: Change in Condition: Abated:

Miscellaneous:

(1) Good
(2) Damaged
(3) Significantly Damaged (25% or more)
(4) No
(5) Yes (If Yes, explain under comments)
(6) Repaired
(7) Removed
(8) Encapsulated
(9) Enclosed
(11) Inaccessible, no inspection data
(12) Other (Explain under comments) psulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Unit B (Maintenance)

District: Center Unified School District

School: District Facility (North)

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	1	NONE DETECTED	4,400 S	BREAKROOM, GARAGE/SHOP, LOFT/STORAGE, MAINTENANCE OFFICE, RESTROOM, STORAGE 2, AND OFFICE 2	(13) SAMPLES HMS-DO-S23-01A-C COLLECTED ON 5-7-92.	Ν
М	9" VINYL FLOOR TILE (TAN) & MASTIC	2	10%	50 S	MAINTENANCE OFFICE 2	(1) (4)	N
м	12" VINYL FLOOR TILE (GRAY/ BROWN) & MASTIC	3	3%	30 S	RESTROOM	(1) (4)	N
М	6" COVE BASE (BROWN) ADHESIVE	117	ASSUMED POSITIVE	20 L	RESTROOM	(1) (4)	Ν
М	12" VINYL FLOOR TILE (WHITE/GRAY) & MASTIC	118	ASSUMED POSITIVE	300 S	BREAK ROOM	(1) (4)	N
М	4" COVE BASE (BLUE) ADHESIVE	119	ASSUMED POSITIVE	56 L	BREAK ROOM	(1) (4)	Ν
S	DRYWALL TEXTURE (STIPPLED STYLE)	139	ASSUMED POSITIVE	680 S	MAINTENANCE OFFICE	(1) (4)	Ν
s	DRYWALL TEXTURE (KNOCKDOWN STYLE)	140	ASSUMED POSITIVE	750 S	BREAK ROOM	(1) (4)	N

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\District Office\District Office HMR.wpd

General Condition: Change in Condition: Abated: Miscellaneous:

(1) Good (4) No (6) Repaired

psulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

Date of Inspection: November 6, 2020

District: Center Unified School District

Inspector: Matt Reilly

Building: Units C & D (Warehouse)

School: District Facility (North)

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	108	ASSUMED POSITIVE	1,000 S	OFFICES 1 & 2	(1) (4)	Ν
м	4" COVE BASE GRAY	120	ASSUMED POSITIVE	100 L	OFFICES 1 & 2	(1) (4)	N
М	SHEET VINYL FLOORING (GRAY)	121	ASSUMED POSITIVE	250 S	OFFICE 1	(2) (5) WATER DAMAGE AT EXTERIOR ENTRY DOOR, FLOOR CRACKING AND SWELLING	N
М	4" COVE BASE (BLACK) ADHESIVE	122	ASSUMED POSITIVE	120 L	DUPLICATING ROOM	(1) (4)	Ν
S	DRYWALL TEXTURE (KNOCKDOWN STYLE)	141	ASSUMED POSITIVE	1,000 S	OFFICES 1 & 2	(1) (4)	Ν
S	DRYWALL TEXTURE (KNOCKDOWN STYLE)	142	ASSUMED POSITIVE	1,000 S	DUPLICATING ROOM	(1) (4)	Ν
М	DRYWALL & JOINT COMPOUND	144	ASSUMED POSITIVE	1,000 S	DUPLICATING ROOM	(1) (4)	N

General Condition: Change in Condition: Abated:

(1) Good

(4) No (6) Repaired

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (1)

Miscellaneous:

psulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

Date of Inspection: November 6, 2020

District: Center Unified School District

School: District Facility (North)

Building: Unit E (Transportation)

Inspector: Matt Reilly

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" VINYL FLOOR TILE (OFF-WHITE) & MASTIC	11	NONE DETECTED	700 S	LOUNGE/OFFICES AND 2 RESTROOMS	(13) SAMPLES HMS-DO-S23-11A & B COLLECTED ON 5-7-92.	Ν
М	DRYWALL & JOINT COMPOUND	12	NONE DETECTED	2,100 S	LOUNGE RESTROOM, LOUNGE/OFFICES, AND TRANSPORTATION SHOP	(13) SAMPLES HMS-DO-S23-12A-C COLLECTED ON 5-7-92.	Ν
М	SHEET VINYL FLOORING	13	NONE DETECTED	80 S	LOUNGE RESTROOM	(13)	Ν
М	CARPET ADHESIVE	150	ASSUMED POSITIVE	200 S	OFFICES	(1) (4)	Ν
S	DRYWALL TEXTURE (KNOCKDOWN STYLE)	151	ASSUMED POSITIVE	600 S	LOUNGE	(1) (4)	N

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\District Office\District Office HMR.wpd

CONDITION CODE

General Condition: Change in Condition: Abated:

(1) Good (4) No

(6) Repaired

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7) (9) Enclosed (10) Isolated & Restricted

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected Miscellaneous: (11) Inaccessible, no inspection data

Date of Inspection: November 6, 2020

District: Center Unified School District

School: District Facility (North)

Inspector: Matt Reilly

Building: Unit F (M.O.T.)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
м	DRYWALL JOINT COMPOUND	104	ASSUMED POSITIVE	1,000 S	ENTRY, KITCHEN, RESTROOM, AND OFFICES 1 & 2	(1) (4)	Ν
М	2' X 4' CEILING PANELS (FISSURE PATTERN)	105	ASSUMED POSITIVE	1,000 S	ENTRY, KITCHEN, RESTROOM, AND OFFICES 1 & 2	(1) (4)	Ν
м	SHEET VINYL FLOORING (GREEN)	106	ASSUMED POSITIVE	860 S	ENTRY, KITCHEN, RESTROOM, AND OFFICES 1 & 2	(1) (4)	N
м	4" COVE BASE (GRAY) ADHESIVE	123	ASSUMED POSITIVE	80 L	ENTRY AND KITCHEN	(1) (4)	Ν
М	4" COVE BASE (BLUE) ADHESIVE	124	ASSUMED POSITIVE	80 L	OFFICES 1 & 2	(1) (4)	Ν
S	DRYWALL TEXTURE (HEAVY STIPPLE PATTERN)	143	ASSUMED POSITIVE	1,000 S	ENTRY, KITCHEN, RESTROOM, AND OFFICES 1 & 2	(1) (4)	N

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\District Office\District Office HMR.wpd

CONDITION CODE

General Condition: Change in Condition: Abated:

Miscellaneous:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (1) (4) No (6) Repaired

psulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

Date of Inspection: November 6, 2020

District: Center Unified School District

School: District Facility (North)

Inspector: Matt Reilly

Building: Unit G (C.S.S.)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	104	ASSUMED POSITIVE	1,000 S	OFFICES 3 & 4, ENTRY 2, AND RESTRICTED ROOM	(1) (4)	Ν
М	2' X 4' CEILING PANELS (FISSURE PATTERN)	105	ASSUMED POSITIVE	920 S	OFFICES 3 & 4, ENTRY 2, AND RESTRICTED ROOM	(1) (4)	Ν
М	4" COVE BASE (GRAY) ADHESIVE	123	ASSUMED POSITIVE	150 L	ENTRY 2, OFFICES 3 & 4, AND RESTRICTED ROOM	(1) (4)	Ν
S	DRYWALL TEXTURE (KNOCKDOWN STYLE)	133	ASSUMED POSITIVE	1,000 S	OFFICES 3 & 4, ENTRY 2, AND RESTRICTED ROOM	(1) (4)	Ν
М	CARPET ADHESIVE	150	ASSUMED POSITIVE	900 S	THROUGHOUT	(1) (4)	Ν

sers/selbert/Entek Consulting Group, Inc/Entekgroup - Documents/Clients/Center USD/20-5551 3 Yr Reinspections/Sites/District Office/District

CONDITION CODE

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7) General Condition: (1) Good Change in Condition: (4) No (6) Repaired (9) Enclosed (10) Isolated & Restricted Abated: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected Miscellaneous:

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Unit H (Restrooms)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	n: Code & Comments	Friable Yes/No
М	SHEET VINYL FLOORING (TAN)	1	ASSUMED POSITIVE	360 S	ALL ROOMS	(1) (4) (11)	CUSTODIAL ROOM IS PATCHED WITH 12" VINYL FLOOR TILE (BLUE). MULTI-USE AND BOY'S & GIRL'S RESTROOMS ARE COVERED WITH LINOLEUM (BLACK/GRAY) AND LINOLEUM (GRAY/CREAM).	Ν
М	DRYWALL & JOINT COMPOUND	2	ASSUMED POSITIVE	360 S	ALL ROOMS	(1) (4) (11)	UNFINISHED DRYWALL IS ASSUMED TO EXIST BEHIND TAGBOARD WALLS.	Ν
S	DRYWALL TEXTURE (ORANGE PEEL STYLE)	135	ASSUMED POSITIVE	360 S	ALL ROOMS	(1) (4)		Ν
М	SHEET VINYL FLOORING (BLACK/GRAY)	136	ASSUMED POSITIVE	40 S	MULTI-USE RESTROOM	(1) (4)		Ν
м	SHEET VINYL FLOORING (GRAY/CREAM)	137	ASSUMED POSITIVE	160 S	BOY'S AND GIRL'S RESTROOMS AND CUSTODIAN ROOM	(1) (4)		Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\District Office\District Office HMR.wpd

CONDITION CODE

(1) Good General Condition: (4) No (6) Repaired Change in Condition: Abated: Miscellaneous:

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7)

(9) Enclosed (10) Isolated & Restricted

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

School: District Facility (South)

District: Center Unified School District

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Unit I (Personnel Office)

District: Center Unified School District

School: District Facility (South)

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	3	ASSUMED POSITIVE	2,000 S	PERSONNEL OFFICE	(11) DRYWALL ASSUMED TO EXIST BEHIND ALL WALL SURFACES.	Ν
М	12" VINYL FLOOR TILE (WHITE/GRAY/ PURPLE) & MASTIC	125	ASSUMED POSITIVE	10 S	PERSONNEL OFFICE	(1) (4)	N
М	4" COVE BASE (BROWN) ADHESIVE	126	ASSUMED POSITIVE	120 L	PERSONNEL OFFICE	(1) (4)	Ν
М	CARPET ADHESIVE	150	ASSUMED POSITIVE	900 S	PERSONNEL OFFICE	(1) (4)	Ν
М	2' X 4' CEILING PANELS	N/A	NOT SUSPECT	960 S	PERSONNEL OFFICE	(13) VINYL COATED FIBERGLASS PANELS	Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\District Office\District Office HMR.wpd

CONDITION CODE

<u>General Condition:</u> <u>Change in Condition:</u>

Miscellaneous:

Abated:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7) (4) No (6) Repaired

psulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

Date of Inspection: November 6, 2020

District: Center Unified School District

School: District Facility (South)

Building: Unit J (Personnel Office)

Inspector: Matt Reilly

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL	3	ASSUMED POSITIVE	2,000 S	PERSONNEL OFFICE	(11) UNFINISHED DRYWALL IS ASSUMED TO EXIST BEHIND TAGBOARD WALLS	Ν
М	12" VINYL FLOOR TILE (WHITE/GRAY/ PURPLE) & MASTIC	125	ASSUMED POSITIVE	20 S	PERSONNEL OFFICE	(1) (4)	Ν
М	4" COVE BASE (BROWN) ADHESIVE	134	ASSUMED POSITIVE	120 L	PERSONNEL OFFICE	(1) (4)	Ν
М	2' X 4' CEILING PANELS	N/A	NOT SUSPECT	900 S	THROUGHOUT	(13) VINYL COATED FIBERGLASS	Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\District Office\District Office HMR.wpd

CONDITION CODE

<u>General Condition:</u> Change in Condition: Abated: Miscellaneous:

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)

(1) Good (4) No (6) Repaired

(6) Repaired (7) Removed (8) Encapsulated (11) Inaccessible, no inspection data (12) Oth osulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Unit K (Special Education)

District: Center Unified School District

School: District Facility (South)

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL	3	ASSUMED POSITIVE	2,000 S	CLASSROOM	(11) UNFINISHED DRYWALL IS ASSUMED TO EXIST BEHIND TAGBOARD WALLS	Ν
М	2' X 4' CEILING PANELS (FISSURE PATTERN)	4	NONE DETECTED	960 S	CLASSROOM	(13) FIBERGLASS	Ν
М	4" COVE BASE (BLUE) ADHESIVE	145	ASSUMED POSITIVE	150 L	CLASSROOM	(1) (4)	Ν
S	DRYWALL TEXTURE (ORANGE PEEL STYLE)	132	ASSUMED POSITIVE	600 S	OFFICE	(1) (4) LOCATED ON TWO WALLS	Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\District Office\District Office HMR.wpd

CONDITION CODE

General Condition: Change in Condition: Abated: Miscellaneous:

(1) Good
(2) Damaged
(3) Significantly Damaged (25% or more)
(4) No
(5) Yes (If Yes, explain under comments)
(6) Repaired
(7) Removed
(8) Encapsulated
(9) Enclosed
(10) Isolated & Restricted
(11) Inaccessible, no inspection data
(12) Other (Explain under comments)
(13) Non-Asbestos/Not Inspected

Date of Inspection: November 6, 2020

District: Center Unified School District

School: District Facility (South)

Building: Unit L (Nutritional Services)

Inspector: Matt Reilly

Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
DRYWALL	3	ASSUMED POSITIVE	2,000 S	OFFICES	(11) UNFINISHED DRYWALL IS ASSUMED TO EXIST BEHIND TAGBOARD WALLS	Ν
4" COVE BASE (BROWN) ADHESIVE	128	ASSUMED POSITIVE	150 L	OFFICES	(1) (4)	Ν
CARPET ADHESIVE	150	ASSUMED POSITIVE	900 S	THROUGHOUT	(1) (4)	Ν
2'X4' CEILING PANELS	N/A	NOT SUSPECT	900 S	THROUGHOUT	(13) VINYL COATED FIBERGLASS PANELS	Ν
•	DRYWALL 4" COVE BASE (BROWN) ADHESIVE CARPET ADHESIVE 2'X4' CEILING	Mat. # DRYWALL 3 4" COVE BASE (BROWN) ADHESIVE CARPET ADHESIVE 2'X4' CEILING N/A	Mat. #DRYWALL3ASSUMED POSITIVE4" COVE BASE (BROWN) ADHESIVE128ASSUMED POSITIVECARPET ADHESIVE150ASSUMED POSITIVE2'X4' CEILINGN/ANOT	Mat. #DRYWALL3ASSUMED POSITIVE2,000 S4" COVE BASE (BROWN) ADHESIVE128ASSUMED POSITIVE150 LCARPET ADHESIVE150ASSUMED POSITIVE900 S2'X4' CEILINGN/ANOT900 S	Mat. #Mat. #DRYWALL3ASSUMED POSITIVE2,000 SOFFICES4" COVE BASE (BROWN) ADHESIVE128ASSUMED POSITIVE150 LOFFICESCARPET ADHESIVE150ASSUMED POSITIVE900 STHROUGHOUT2'X4' CEILINGN/ANOT900 STHROUGHOUT	Mat. #Mat. #Mat. #DRYWALL3ASSUMED POSITIVE2,000 SOFFICES(11)UNFINISHED DRYWALL IS ASSUMED TO EXIST BEHIND TAGBOARD WALLS4" COVE BASE (BROWN) ADHESIVE128ASSUMED POSITIVE150 LOFFICES(1) (4)CARPET ADHESIVE150ASSUMED POSITIVE900 STHROUGHOUT(1) (4)2'X4' CEILINGN/ANOT900 STHROUGHOUT(13)VINYL COATED FIBERGLASS PANELS

CONDITION CODE

General Condition:	(1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition:	(4) No (5) Yes (If Yes, explain under comments)
Abated:	(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous:	(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: November 6, 2020

District: Center Unified School District

School: District Facility (South)

Building: Unit M (Conference Room)

Inspector: Matt Reilly

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL	3	ASSUMED POSITIVE	2,000 S	THROUGHOUT	(11) UNFINISHED DRYWALL IS ASSUMED TO EXIST BEHIND TAGBOARD WALLS	Ν
М	4" COVE BASE BLUE	129	ASSUMED POSITIVE	120 L	THROUGHOUT	(1) (4)	Ν
М	CARPET ADHESIVE	150	ASSUMED POSITIVE	900 S	THROUGHOUT	(1) (4)	Ν
М	2'X4' CEILING PANELS	N/A	NOT SUSPECT	900 S	THROUGHOUT	(13) VINYL COATED FIBERGLASS PANELS	Ν

C:Users/selbert/Entek Consulting Group, Inc/Entekgroup - Documents/Clients/Center USD/20-5551 3 Yr Reinspections/Sites/District Office/District Office HMR.wpd

CONDITION CODE

General Condition:	(1) Good	(2) Damaged (3) Significantly Damaged (25% or more)	
Change in Condition:	(4) No	(5) Yes (If Yes, explain under comments)	
Abated:	(6) Repaired	(7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted	
Miscellaneous:	(11) Inaccessib	e, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected	

Date of Inspection: November 6, 2020

District: Center Unified School District

School: District Facility (South)

Building: Unit N (Conference Room)

Inspector: Matt Reilly

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL	10	ASSUMED POSITIVE	2,000 S	THROUGHOUT	(11) UNFINISHED DRYWALL IS ASSUMED TO EXIST BEHIND TAGBOARD WALLS	Ν
М	4" COVE BASE BLUE	130	ASSUMED POSITIVE	120 L	THROUGHOUT	(1) (4)	Ν
М	CARPET ADHESIVE	150	ASSUMED POSITIVE	900 S	THROUGHOUT	(1) (4)	Ν
М	2'X4' CEILING PANELS	N/A	NOT SUSPECT	900 S	THROUGHOUT	(13) VINYL COATED FIBERGLASS PANELS	N

C:Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\District Office\District Office HMR.wpd

CONDITION CODE

	(1) Good	(2)	Damaged ((3) Significantly Damaged (25% or more)
Change in Condition:	(4) No	(5)	Yes (If Yes, e	, explain under comments)
Abated:	(6) Repaired	(7)	Removed ((8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous:	(11) Inaccessibl	è, 'n	o inspection d	data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Center Unified School District

Date of Inspection: November 6, 2020

Inspector: Matt Reilly


School: District Facility (South)

Building: Unit O (Instructional Services)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL	10	ASSUMED POSITIVE	2,000 S	THROUGHOUT	(11) UNFINISHED DRYWALL IS ASSUMED TO EXIST BEHIND TAGBOARD WALLS	Ν
М	4" COVE BASE (GREEN)	131	ASSUMED POSITIVE	120 L	THROUGHOUT	(1) (4)	Ν
М	CARPET ADHESIVE	150	ASSUMED POSITIVE	900 S	THROUGHOUT	(1) (4)	Ν
М	2'X4' CEILING PANELS	N/A	NOT SUSPECT	900 S	THROUGHOUT	(13) VINYL COATED FIBERGLASS PANELS	N/A

CONDITION CODE

General Condition:
Change in Condition:(1) Good(2) Damaged(3) Significantly Damaged(25% or more)Abated:
Miscellaneous:(4) No(5) Yes (If Yes, explain under comments)(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & RestrictedMiscellaneous:(11) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected



Dudley (Arthur) Elementary School

RECORD OF FRIABLE AND NON-FRIABLE ACM (FORM B)

	THRE	E-YEAR R	EINSF	PECTIO	N			
						DS CODE 4-73973-6032	908	
SCHOOI Dudley	L (Arthur S.) Elementary School					CHOOL PHONE 916) 338-6470		
ADDRES 8000 Az	SS (NUMBER) (STREET)		(CITY) Antelope	, CA	(ZIP) 95843		
	Each building and functional space with friable completion of <u>FORM C</u> (PHYSICAL AND HAZ/ ACBM). Indicate location of material on bluepr copy (Sec. 763.93).	-IMPOR ACBM or fi ARD ASSE int, diagran	riable a SSMEI	ssumed A	ACBM liste RIABLE AC square or	ed on this form CBM OR FRIAI inear feet, and	requires 3LE ASSUM I attach a	ED
		CHE	ECK O	NE		CHEC	K ONE	
LINE	BUILDING NAME & FUNCTIONAL SPACE	SUR-			ļ	ACBM	ASSUME	D ACBM
	(Indicate Address if Different From Above)	FACING	TSI	MISC	FRIABLE	NON- FRIABLE	FRIABLE	NON- FRIABLE
1.	CAFETERIA/MP			х		х		х
2.	CLASSROOMS A1-A6			Х				х
3.	CLASSROOM A7			Х				х
4.	CLASSROOMS B1-B6			х		х		х
5.	CLASSROOMS C1-C6			Х				Х
6.	CLASSROOM C7			Х				Х
7.	CLASSROOM D7			Х		х		Х
8.	CLASSROOM E8			Х		Х		Х
9.	ROOM F9 (LIBRARY)	х		Х				Х
10.	CLASSROOM 10			Х		Х		Х
11.	OFFICE	х		Х				Х
12.	PORTABLES M1-M12	х		Х				х
13.	PORTABLES T3-T5	х		Х				Х
14.	E11 STORAGE SHED NO SUSPECT MATERIALS							
15.	C-TRAIN STORAGE NO SUSPECT MATERIALS							
16.								
17.								
	C:\Users\selbert\Entek Consulting Group, Inc\E	ntekgroup - Doo	cuments\C	lients\Center	USD\20-5551	3 Yr Reinspections	sites\Dudley ES\Di	Jdley Form B.wpd

See attached "Homogeneous Materials Records" for all materials and their locations by building. On Form B all buildings are listed, and a summary of all non-friable and friable material is provided. Friable materials and their locations are listed separately under each building on Form B.

District: Center Unified School District

School: Dudley Elementary School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Cafeteria/MP

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition	n: Code & Comments	Friable Yes/No
S	PLASTER	1	NONE DETECTED	5,250 S	MPR/STAGE, SUB-STAGE, RESTROOM, STORAGE, AND KITCHEN	(13)	REPRESENTED BY SAMPLES HMS-DE- S23-01A-E COLLECTED ON 5-11-92.	Ν
М	12" CEILING TILE (FISSURE PATTERN)	5	NONE DETECTED	3,200 S	MPR/STAGE	(13)	REPRESENTED BY SAMPLES HMS-DE- S23-05A-C COLLECTED ON 5-11-92.	Ν
М	PIPEWRAP (PAPER)	6	NONE DETECTED	50 L	SUB-STAGE	(13)	SAMPLES HMS-C93-04A-CF.	Ν
М	12" VINYL FLOOR TILE (GRAY) & MASTIC	172	ASSUMED POSITIVE	2,400 S	MPR	(1) (4)		Ν
М	EPOXY (TAN) FLOOR COATING	173	ASSUMED POSITIVE	400 S	KITCHEN	(1) (4)		Ν
М	6" VINYL COVE BASE MASTIC (BROWN)	188	<1% FIBROUS TREMOLITE	100 L	MPR	(1) (4)	SAMPLE ECG-07-735-24A COLLECTED ON 2-21-08.	Ν
S	STUCCO	189	NONE DETECTED	UNDETERMINED	EXTERIOR UNDERSIDE OF PORTICO AT MPR	(13)	SAMPLES ECG-07-735-32A & B COLLECTED ON 2-21-08.	Ν
М	12" VINYL FLOOR TILE (LIGHT BLUE) & MASTIC	202	ASSUMED POSITIVE	40 S		(1) (4)	Contor USD120 EEE4 2 Vr. Baingongiona (Sitra) Dudlay ES1	N

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Dudley ES\Dudley HMR.wpd

CONDITION CODE

General Condition: Change in Condition: Abated:

Miscellaneous:

 Good
 Damaged
 Significantly Damaged
 or more)
 No
 Yes (If Yes, explain under comments)
 Repaired
 Removed
 Encapsulated
 Enclosed
 Enclosed
 Control (12)
 Enclosed
 (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Classrooms A1-A6

District: Center Unified School District

School: Dudley Elementary School

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	1	NONE DETECTED	11,000 S	CLASSROOMS A1-A6	(13) REPRESENTED BY SAMPLE HMS-DE- S23-01E COLLECTED ON 5-11-92 AND ECG-07-735-01B COLLECTED ON 6-4-08.	Ν
М	12" CEILING TILE (FISSURE PATTERN)	5	NONE DETECTED	1,280 S	CLASSROOMS A1-A6	(13) REPRESENTED BY SAMPLES HMS-DE- S23-05A-C COLLECTED ON 5-11-92.	Ν
М	BLACK ROOF MASTIC	190	NONE DETECTED	UNDETERMINED	ROOF	 (12) NOT COVERED BY AHERA (13) SAMPLE ECG-07-735-187A COLLECTED ON 2-21-08. 	Ν
S	DRYWALL TEXTURE	191	NONE DETECTED	UNDETERMINED	CLASSROOMS A5 & A6	(13) SAMPLES ECG-07-735-34A-C COLLECTED ON 2-21-08.	Ν
М	CARPET ADHESIVE (YELLOW)	192	NONE DETECTED	UNDETERMINED	CLASSROOM A1	(13) SAMPLE ECG-07-735-40B COLLECTED ON 2-21-08.	Ν
М	12" VINYL FLOOR TILE (GRAY MOTTLED) & MASTIC	203	ASSUMED POSITIVE	1,080 S	CLASSROOMS A1-A6	(1) (4)	N
М	6" COVE BASE (GRAY) ADHESIVE	204	ASSUMED POSITIVE	720 L	CLASSROOMS A1-A6	(1) (4)	Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Dudley ES\Dudley HMR.wpd

CONDITION CODE

General Condition:
Change in Condition:(1) Good(2) Damaged(3) Significantly Damaged(25% or more)Abated:
Miscellaneous:(4) No(5) Yes (If Yes, explain under comments)(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & RestrictedMiscellaneous:(11) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected

District: Center Unified School District

School: Dudley Elementary School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Classroom A7

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL	98	ASSUMED POSITIVE	2,000 S	CLASSROOM A7	(11) DRYWALL IS ASSUMED TO EXIST BEHIND ALL WALL SURFACES.	Ν
М	4" COVE BASE (BLUE)	174	ASSUMED POSITIVE	120 L	CLASSROOM A7	(1) (4)	Ν
М	CARPET ADHESIVE	211	ASSUMED POSITIVE	900 S	CLASSROOM A7	(1) (4)	Ν
М	2'X4' CEILING PANELS	N/A	NOT SUSPECT	900 S	CLASSROOM A7	(13) VINYL COATED FIBERGLASS PANELS	N

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Dudley ES\Dudley HMR.wpd

CONDITION CODE

General Condition: Change in Condition: Abated: Miscellaneous:

(1) Good

(4) No (6) Repaired

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7) (9) Enclosed (10) Isolated & Restricted

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Center Unified School District

School: Dudley Elementary School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Classrooms B1-B6

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	n: Code & Comments	Friable Yes/No
S	PLASTER	1	NONE DETECTED	12,000 S	CLASSROOMS B1-B6	(13)	REPRESENTED BY SAMPLES HMS-DE- S23-01A-E COLLECTED ON 5-11-92.	Ν
М	12" CEILING TILE (FISSURE PATTERN)	5	NONE DETECTED	6,000 S	CLASSROOMS B1-B6	(13)	REPRESENTED BY SAMPLES HMS-DE- S23-05A-C COLLECTED ON 5-11-92.	Ν
М	DRYWALL & JOINT COMPOUND	193	NONE DETECTED	UNDETERMINED	CLASSROOM B1	(13)	SAMPLE ECG-07-735-33A COLLECTED ON 2-21-08.	Z
М	ROOF MASTIC (BLACK)	194	1-5%	UNDETERMINED	ROOF	(12) (1)	NOT COVERED UNDER AHERA SAMPLE ECG-07-735-187A COLLECTED ON 2-21-08.	Ν
М	CARPET ADHESIVE (YELLOW)	195	NONE DETECTED	UNDETERMINED	CLASSROOM B1	(13)	SAMPLE ECG-07-735-40A COLLECTED ON 6-2-08.	Ν
М	12" VINYL FLOOR TILE (GRAY) & MASTIC	203	ASSUMED POSITIVE	1,080 S	CLASSROOMS B1-B6	(1) (4)		Ν
М	6" COVE BASE (GRAY) ADHESIVE	204	ASSUMED POSITIVE	720 L	CLASSROOMS B1-B6	(1) (4)		Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Dudley ES\Dudley HMR.wpd

CONDITION CODE

General Condition:
Change in Condition:
Abated:(1) Good
(2) Damaged
(3) Significantly Damaged (25% or more)
(4) No
(5) Yes (If Yes, explain under comments)
(6) Repaired
(7) Removed
(8) Encapsulated
(12) Other (Explain under comments)
(13) Non-Asbestos/Not Inspected

District: Center Unified School District

School: Dudley Elementary School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Classrooms C1-C6

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" CEILING TILE (FISSURE PATTERN)	5	NONE DETECTED	6,000 S	CLASSROOMS C1-C6	(13) SAMPLE HMS-DE-S23-05C COLLECTED ON 5-11-92.	Ν
S	PLASTER	15	NONE DETECTED	10,000 S	CLASSROOMS C1-C5	(13) SAMPLES HMS-C93-03A-C.	Ν
М	DRYWALL & JOINT COMPOUND	16	NONE DETECTED	2,000 S	CLASSROOM C6	(13) SAMPLES HMS-DE-S23-16A-C COLLECTED ON 5-11-92.	Ν
М	ROOF MASTIC (BLACK)	196	NONE DETECTED	UNDETERMINED	ROOF	 (12) NOT COVERED UNDER AHERA (13) SAMPLE ECG-07-735-187C COLLECTED ON 2-21-08. 	Ν
М	12" VINYL FLOOR TILE (GRAY) & MASTIC	203	ASSUMED POSITIVE	1,080 S	CLASSROOMS C1-C6	(1) (4)	Ν
М	6" COVE BASE (GRAY) ADHESIVE	204	ASSUMED POSITIVE	720 L	CLASSROOMS C1-C6	(1) (4)	Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Dudley ES\Dudley HMR.wpd

CONDITION CODE

General Condition: Change in Condition: Abated:

Miscellaneous:

(1) Good

(4) No (6) Repaired

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7)

psulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

District: Center Unified School District

School: Dudley Elementary School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Classroom C7

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location		Friable Yes/No
М	DRYWALL	98	ASSUMED POSITIVE	2,000 S	CLASSROOM C7	(11) UNFINISHED DRYWALL IS ASSUMED TO EXIST BEHIND ALL TAGBOARD.	Ν
М	4" COVE BASE (BLUE)	176	ASSUMED POSITIVE	120 L	CLASSROOM C7	(1) (4)	Ν
М	CARPET ADHESIVE	211	ASSUMED POSITIVE	900 S	CLASSROOM C7	(1) (4)	Ν
М	2'X4' CEILING PANELS	N/A	NOT SUSPECT	900 S	CLASSROOM C7	(13) VINYL COATED FIBERGLASS PANELS	Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Dudley ES\Dudley HMR.wpd

CONDITION CODE

General Condition:
Change in Condition:(1) Good(2) Damaged(3) Significantly Damaged(25% or more)Abated:
Miscellaneous:(4) No(5) Yes (If Yes, explain under comments)(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & Restricted(1) Good(1) Good(2) Damaged(3) Significantly Damaged(25% or more)(2) Damaged(2) Damaged(2) Abated:
Miscellaneous:(1) No(5) Yes (If Yes, explain under comments)(10) Isolated & Restricted(1) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected

Date of Inspection: November 6, 2020

District: Center Unified School District

School: Dudley Elementary School

Inspector: Matt Reilly

Building: Classroom D-7

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	1	NONE DETECTED	3,300 S	CLASSROOM 7, RESTROOM, D12 AND CUSTODIAL	(13) SAMPLE HMS-DE-S23-01E COLLECTED ON 5-11-92.	Ν
М	12" CEILING TILE (FISSURE PATTERN)	5	NONE DETECTED	1,140 S	CLASSROOM 7, RESTROOM, AND CUSTODIAL	(13) SAMPLE HMS-DE-S23-05B COLLECTED ON 5-11-92.	Ν
М	DRYWALL & JOINT COMPOUND	10	1-5% IN JOINT COMPOUND	289 S	CUSTODIAL AND D12	(1) (4)	Ν
М	9" VINYL FLOOR TILE (GRAY) & MASTIC	13	10%	1,100 S	CLASSROOM 7	 (11) COVERED WITH CARPET IN CLASSROOM (7) SERVER ROOM & RESTROOM 	N
М	12" VINYL FLOOR TILE (LIGHT BLUE) & MASTIC	168	ASSUMED POSITIVE	150 S	CLASSROOM 7	(11) COVERED WITH CARPET & MATERIAL 203	Ν
М	12" VINYL FLOOR TILE (GRAY) & MASTIC	203	ASSUMED POSITIVE	180 S	CLASSROOM 7	(1) (4)	Ν
М	6" COVE BASE (GRAY) ADHESIVE	204	ASSUMED POSITIVE	120 L	CLASSROOM 7	(1) (4)	N
М	CARPET ADHESIVE	211	ASSUMED POSITIVE	720 S	CLASSROOM 7	(1) (4)	Ν

C:Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Dudley ES\Dudley HMR.wpd CONDITION CODE

General Condition: Change in Condition: Abated: Miscellaneous:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7)

(4) No (6) Repaired

(9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

District: Center Unified School District

School: Dudley Elementary School

Inspector: Matt Reilly

Building: Classroom E-8 Page 1 of 2

Date of Inspection: November 6, 2020

							-	ugo 1 01 2
Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	n: Code & Comments	Friable Yes/No
S	PLASTER	1	NONE DETECTED	4,000 S	CLASSROOM E-8, RESTROOMS, AND MECHANICAL ROOM	(13)	SAMPLE HMS-DE-S23-01D COLLECTED ON 5-11-92.	N
М	12" CEILING TILE (FISSURE PATTERN)	5	NONE DETECTED	1,200 S	CLASSROOM E-8	(13)	REPRESENTED BY SAMPLES HMS-05A-C COLLECTED ON 5-11-92.	N
М	9" VINYL FLOOR TILE (BEIGE) & MASTIC	12	ASSUMED POSITIVE	1,200 S	CLASSROOM E-8	(11) (4)	COVERED WITH CARPET.	N
М	12" VINYL FLOOR TILE (BLUE/GRAY) & YELLOW MASTIC	162	NONE DETECTED	200 S	MECHANICAL ROOM AND CLASSROOM 8	(13)	SAMPLE ECG-07-735-162A COLLECTED ON 2-21-08.	Ν
М	4" COVE BASE (GRAY) ADHESIVE	163	ASSUMED POSITIVE	40 L	MECHANICAL ROOM	(1) (4)		N
М	DRYWALL & JOINT COMPOUND	164	ASSUMED POSITIVE	900 S	MECHANICAL ROOM AND CUSTODIAL ROOM	(1) (4)		N
М	6" COVE BASE (GRAY) ADHESIVE	165	ASSUMED POSITIVE	120 L	CLASSROOM E-8	(1) (4)		N

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Dudley ES\Dudley HMR.wpd

CONDITION CODE

General Condition: Change in Condition: Abated: Miscellaneous:

(4) No

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7) (6) Repaired

osulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

Date of Inspection: November 6, 2020

District: Center Unified School District

School: Dudley Elementary School

Inspector: Matt Reilly

Building: Classroom E-8 Page 2 of 2

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	ROOF MASTIC (BLACK)	197	1-5% CHRYSOTILE	UNDETERMINED	ROOF	 (12) NOT COVERED UNDER AHERA (1) SAMPLE ECG-07-735-187E COLLECTED ON 2-21-08. 	Ν
М	CARPET ADHESIVE	211	ASSUMED POSITIVE	600 S	CLASSROOM E-8	(1)	Ν
М	12" VINYL FLOOR TILE (GRAY MOTTLED) & MASTIC	212	ASSUMED POSITIVE	300 S	CLASSROOM E-8	(1)	Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Dudley ES\Dudley HMR.wpd

CONDITION CODE

General Condition:
Change in Condition:
Abated:(1) Good
(2) Damaged
(3) Significantly Damaged (25% or more)Abated:
Miscellaneous:(4) No
(5) Yes (If Yes, explain under comments)
(6) Repaired
(7) Removed
(8) Encapsulated
(12) Other (Explain under comments)
(13) Non-Asbestos/Not Inspected

District: Center Unified School District

School: Dudley Elementary School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Room F-9 (Library)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	n: Code & Comments	Friable Yes/No
S	PLASTER	1	NONE DETECTED	3,000 S	LIBRARY & STORAGE AREA	(13)	SAMPLE HMS-DE-S23-01C COLLECTED ON 5-11-92.	Ν
М	12" CEILING TILE (FISSURE PATTERN)	5	NONE DETECTED	1,840 S	LIBRARY & STORAGE AREA	(13)	SAMPLE HMS-DE-S23-05A COLLECTED ON 5-11-92.	Ν
М	6" COVE BASE (GRAY) ADHESIVE	156	ASSUMED POSITIVE	40 L	LIBRARY STORAGE ROOM	(1) (4)		Ν
S	TEXTURE (SPLATTER STYLE)	177	ASSUMED POSITIVE	3,000 S	LIBRARY & STORAGE AREA	(1) (4)		Ν
М	12" VINYL FLOOR TILE (GRAY MOTTLED) & MASTIC	203	ASSUMED POSITIVE	200 S	STORAGE AREA	(1) (4)		Ν
М	CARPET ADHESIVE	211	ASSUMED POSITIVE	1,200 S	LIBRARY	(1) (4)		Ν
М	6" COVE BASE (BLUE) ADHESIVE	213	ASSUMED POSITIVE	150 L	LIBRARY	(1) (4)		Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Dudley ES\Dudley HMR.wpd

CONDITION CODE

General Condition: (1) Good Change in Condition: (4) No (6) Repaired Abated: Miscellaneous:

(2) Damaged (3) Significantly Damaged (25% or more)(5) Yes (If Yes, explain under comments)

(9) Enclosed (10) Isolated & Restricted

(6) Repaired (7) Removed (8) Encapsulated (11) Inaccessible, no inspection data (12) Oth (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Center Unified School District

School: Dudley Elementary School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Classroom 10

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	on: Code & Comments	Friable Yes/No
S	PLASTER	1	NONE DETECTED	800 S	CLASSROOM 10	(13)	SAMPLE HMS-DE-S23-01B COLLECTED ON 5-11-92 AND SAMPLE ECG-07-735-1A COLLECTED ON 2-21-08.	Ν
м	12" CEILING TILE (FISSURE PATTERN)	5	NONE DETECTED	1,850 S	CLASSROOM 10	(13)	REPRESENTED BY SAMPLES HMS-DE- S23-05A-C COLLECTED ON 5-11-92.	Ν
М	SHEET VINYL FLOORING (CREAM WITH BLUE SPECKS)	179	NONE DETECTED	60 S	MEN'S AND WOMEN'S RESTROOM	(13)	SAMPLE ECG-07-735-21A COLLECTED ON 2-2-21-08.	Ν
М	6" COVE BASE (GRAY) ADHESIVE	198	1% FIBROUS TREMOLITE	100 L	CLASSROOM 10	(1) (4)	SAMPLE ECG-07-735-8A COLLECTED ON 2-21-08.	Ν
м	DRYWALL & JOINT COMPOUND	199	NONE DETECTED	UNDETERMINED	CLASSROOM 10 & MEN'S RESTROOM	(13)	SAMPLE ECG-07-735-14A & B COLLECTED ON 2-21-08.	Ν
S	DRYWALL TEXTURE	200	NONE DETECTED	UNDETERMINED	MEN'S RESTROOM AND PTA ROOM	(13)	SAMPLE ECG-07-735-20A & B COLLECTED ON 2-21-08.	Ν
М	12" VINYL FLOOR TILE (GRAY MOTTLED) & MASTIC	203	ASSUMED POSITIVE	40 S	CLASSROOM 10	(1) (4)	LOCATED AT KITCHENETTE	Ζ
М	CARPET ADHESIVE	211	ASSUMED POSITIVE	1,000 S	CLASSROOM 10	(1) (4)		Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Dudley ES\Dudley HMR.wpd

CONDITION CODE

General Condition: Change in Condition:

Abated:

(1) Good (4) No

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (1) (6) Repaired

psulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data Miscellaneous:

District: Center Unified School District

School: Dudley Elementary School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Office

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	1	NONE DETECTED	2,400 S	ADMINISTRATION OFFICE	(13) SAMPLE HMS-DE-S23-01A COLLECTED ON 5-11-92.	N
М	12" CEILING TILE (FISSURE PATTERN)	5	NONE DETECTED	1,700 S	ADMINISTRATION OFFICE	(13) REPRESENTED BY SAMPLES HMS-DE- S23-05A-C COLLECTED ON 5-11-92.	N
М	6" COVE BASE (GRAY) ADHESIVE	152	ASSUMED POSITIVE	200 L	ADMINISTRATION OFFICE, OFFICES 1-4, AND RESTROOMS 2 & 3	(1) (4)	N
М	DRYWALL & JOINT COMPOUND	153	ASSUMED POSITIVE	4,000 S	ADMINISTRATION OFFICE, OFFICES 1-4, RESTROOM 1, NURSE'S OFFICE, AND NURSE'S RESTROOM	(1) (4)	N
S	DRYWALL TEXTURE (ORANGE PEEL STYLE)	180	ASSUMED POSITIVE	4,000 S	ADMINISTRATION OFFICE, OFFICES 1-4, RESTROOM 1, NURSE'S OFFICE, AND NURSE'S RESTROOM	(1) (4)	N
М	ROOF MASTIC (BLACK)	201	1-5% CHRYSOTILE	UNDETERMINED	ROOF	(12) NOT COVERED UNDER AHERA SAMPLE ECG-07-735-187D COLLECTED ON 2-21-08.	N
М	12" VINYL FLOOR TILE (GRAY MOTTLED) & MASTIC	203	ASSUMED POSITIVE	300 S	OFFICE ENTRY, NURSE, RESTROOM	(1) (4)	N
М	12" CEILING TILE (1/8" HOLES PATTERN)	214	ASSUMED POSITIVE	50 S	MEN & WOMEN RESTROOMS AT EXTERIOR OF BUILDING	(1) (4)	N

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Dudley ES\Dudley HMR.wpd

CONDITION CODE

General Condition:
Change in Condition:(1) Good(2) Damaged(3) Significantly Damaged (25% or more)Abated:
Miscellaneous:(4) No(5) Yes (If Yes, explain under comments)(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(11) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected

Date of Inspection: November 6, 2020

District: Center Unified School District

School: Dudley Elementary School

Inspector: Matt Reilly

Building: Portables M1-M12 Page 1 of 2

								l ugo i oi
Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	n: Code & Comments	Friable Yes/No
М	DRYWALL	150	ASSUMED POSITIVE	7,500 S	PORTABLES M1-M8	(11)	UNFINISHED DRYWALL IS ASSUMED TO EXIST BEHIND TAGBOARD.	N
М	4" COVE BASE (GRAY) ADHESIVE	170	ASSUMED POSITIVE	720 L	PORTABLES M5, M7, M8 & M12	(1) (4)		Ν
М	12" VINYL FLOOR TILE (WHITE/BLUE) & MASTIC	183	ASSUMED POSITIVE	10 S	PORTABLE M6	(11)	ASSUMED TO EXIST BENEATH SELF ADHESIVE CARPET SQUARES.	N
М	12" VINYL FLOOR TILE (GRAY MOTTLED) & MASTIC	203	ASSUMED POSITIVE	1,200 S	PORTABLES M1 & M2	(1) (4)		N
М	SHEET VINYL (MULTI- COLORED)	205	ASSUMED POSITIVE	300 S	PORTABLES M1 & M2	(5) (1) (4)	MATERIAL NOT FOUND IN M1 MATERIAL LOCATED AT KITCHEN AREA, RESTROOMS AND OFFICE	N
М	DRYWALL	206	ASSUMED POSITIVE	500 S	PORTABLE M2	(1) (4)		N
S	WALL TEXTURE (KNOCKDOWN STYLE)	207	ASSUMED POSITIVE	500 S	PORTABLE M2	(1) (4)		N

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Dudley ES\Dudley HMR.wpd

CONDITION CODE

General Condition: Change in Condition: Abated:

Miscellaneous:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7)

(4) No (6) Repaired

(9) Enclosed (10) Isolated & Restricted

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

District: Center Unified School District

School: Dudley Elementary School

Inspector: Matt Reilly

Building: Portables M1-M12 Page 2 of 2

-		-					age 2 61 2
Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	4" COVE BASE (BLUE) ADHESIVE	208	ASSUMED POSITIVE	120 L	PORTABLES M3, M4, & M6	(1) (4)	Ν
М	4" COVE BASE (LIGHT BROWN) ADHESIVE	209	ASSUMED POSITIVE	360 L	PORTABLES M9, M10 & M11	(1) (4)	Ν
М	2' X 4' CEILING PANELS	210	ASSUMED POSITIVE	4,000 S	PORTABLES M5, M6, M9, M10, M11 & M12	(1) (4)	Ν
М	CARPET ADHESIVE	211	ASSUMED POSITIVE	7,200 S	PORTABLES M3, M4, M5, M7, M9, M10, M11 & M12	(1) (4)	Ν
М	4" COVE BASE (BROWN) ADHESIVE	215	ASSUMED POSITIVE	240 L	PORTABLES M1 & M2	(1) (4)	Ν
М	2'X4' CEILING PANELS	N/A	NOT SUSPECT	3,000 S	PORTABLES M1, M3, M7, M8, M11 & M12	(13) VINYL COATED FIBERGLASS PANELS	N/A

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Dudley ES\Dudley HMR.wpd

CONDITION CODE

General Condition: Change in Condition: (1) Good

(4) No

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7) (6) Repaired

Abated: psulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data Miscellaneous:

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection: November 6, 2020

District: Center Unified School District

School: Dudley Elementary School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Portables T3-T5

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL	151	ASSUMED POSITIVE	3,700 S	PORTABLES T3-T5	(11) DRYWALL IS ASSUMED TO EXIST BEHIND TAGBOARD IN T3 & T5.	Ν
М	4" COVE BASE (BLUE) ADHESIVE	171	ASSUMED POSITIVE	400 L	PORTABLES T3-T5	(1) (4)	Ν
М	2' X 4' CEILING PANELS	184	NONE DETECTED	2,400 S	PORTABLES T3-T5	(13) SAMPLE ECG-07-735-184A COLLECTED ON 2-21-08.	Y
М	DRYWALL & JOINT COMPOUND	185	ASSUMED POSITIVE	2,000 S	PORTABLE T4	(1) (4)	Ν
S	TEXTURE (KNOCKDOWN STYLE)	186	ASSUMED POSITIVE	2,000 S	PORTABLE T4	(1) (4)	Ν
М	CARPET ADHESIVE	211	ASSUMED POSITIVE	2,500 S	PORTABLES T3 - T5	(1) (4)	Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Dudley ES\Dudley HMR.wpd

CONDITION CODE

General Condition: Change in Condition:


- (1) Good (4) No
- (2) Damaged (3) Significantly Damaged (25% or more)(5) Yes (If Yes, explain under comments)

Abated:

Miscellaneous:

- (6) Repaired (7) Removed (8) Encapsulated
 - (9) Enclosed (10) Isolated & Restricted
- (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Dudley (Arthur S.) Elementary School



Center Unified School District Dudley (Arthur S.) Elementary School 8000 Aztec Way Antelope, CA 95843


•

Ν

Entek Consulting Group, Inc. 4200 Rocklin Road, Suite 7 Rocklin, CA 95677 Map Not to Scale

Three-Year AHERA Reinspection Conducted by Matt Reilly On November 6, 2020 Project Number 20-5551

Cloud\ Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Dudley ES



RECORD OF FRIABLE AND NON-FRIABLE ACM (FORM B)

THREE-YEAR REINSPECTION

						DS CODE 4-73973-6032	916	
	DL Charter School - NO LONGER IN OPERATION N GENERAL DISTRICT OFFICES	N AS OF JI	JLY 20	17 - FAC		CHOOL PHONE 916) 338-6450		
ADDRE 8300 V	SS (NUMBER) (STREET Vatt Avenue	-)		(CITY) Antelope	, CA	(ZIP) 95843		
	Each building and functional space with friable completion of <u>FORM C</u> (PHYSICAL AND HAZ ACBM). Indicate location of material on bluep copy (Sec. 763.93).	ARD ASSE	riable a SSMEI	ssumed ANT OF FF	RIABLE AC	BM OR FRIA	BLÉ ASSUM	ED
		CHE		NE		CHEC	K ONE	
LINE	BUILDING NAME & FUNCTIONAL SPACE	SUR-			Ą	СВМ	ASSUME	D ACBM
	(Indicate Address if Different From Above)	FACING	TSI	MISC	FRIABLE	NON- FRIABLE	FRIABLE	NON- FRIABLE
1.	PORTABLE CLASSROOMS 34-38 DISTRICT MUST CERTIFY							
2.	PORTABLE CLASSROOM 50 DISTRICT MUST CERTIFY							
3.	UNIT B & C			х				Х
4.	UNIT H (PORTABLE CLASSROOMS 25-33) DISTRICT MUST CERTIFY							
5.	UNIT R DISTRICT MUST CERTIFY							
6.	UNIT S (PORTABLE CLASSROOMS 16-18) DISTRICT MUST CERTIFY							
7.	UNIT X (PORTABLE CLASSROOMS 11-14)			х				Х
8.	UNIT Y (PORTABLE CLASSROOMS 40-43)			х				Х
9.								
10.								
11.								
12.								
13.								
14.								

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Global Charter School\Global Charter Form B.wpd

See attached "Homogeneous Materials Records" for all materials and their locations by building. On Form B all buildings are listed, and a summary of all non-friable and friable material is provided. Friable materials and their locations are listed separately under each building on Form B.

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

District: Center Unified School District

School: Global Charter School (No Longer in Operation as of July 2017)

Building: Units B & C (Charter Schools Administration)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	on: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	1	NONE DETECTED	6,100 S	MUSIC ROOM, CLASSROOM 45, AND ARTS & CRAFTS	(13)	SAMPLE HMS-CJHS-S23-01E COLLECTED ON 5-1-92.	Ν
М	12" CEILING TILE (FISSURE PATTERN)	4	NONE DETECTED	1,600 S	MUSIC ROOM AND CLASSROOM 45	(13)	REPRESENTED BY SAMPLES HMS-CJHS-S23- 04A-C COLLECTED ON 5-1-92.	N
М	12" VINYL FLOOR TILE (OFF-WHITE) & MASTIC	7	NONE DETECTED	2,700 S	MUSIC ROOM, CLASSROOM 45, AND ARTS & CRAFTS	(13)	REPRESENTED BY SAMPLE HMS-CJHS-07A COLLECTED ON 5-1-92.	N
М	12" VINYL FLOOR TILE (BLUE) & MASTIC	10	NONE DETECTED	300 S	MUSIC ROOM	(13)	SAMPLE HMS-CJHS-S23-10A COLLECTED ON 5-1-92.	N
М	4" COVE BASE (BLACK) ADHESIVE	127	ASSUMED POSITIVE	200 L	CLASSROOM 44	(1) (4)		Ν
М	2' X 4' CEILING PANELS (FISSURE PATTERN)	144	ASSUMED POSITIVE	960 S	ARTS & CRAFTS ROOM (MIDDLE ROOM)	(1) (4)	WATER STRAIN IN STORAGE OF CRAFT ROOM.	N
S	WALL TEXTURE (ORANGE PEEL STYLE)	145	ASSUMED POSITIVE	2,000 S	CLASSROOMS 44 & 45	(1) (4)		Ν
S	WALL/CEILING TEXTURE (KNOCKDOWN)	147	ASSUMED POSITIVE	500 S	ROOM 45A AT STORAGE	(1) (4)		N
					C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Docume	ents\Clients\C	enter USD\20-5551 3 Yr Reinspections\Sites\Global Charter School\Globa	al Charter HMR.wpd

General Condition: Change in Condition: Abated:

Miscellaneous:

(1) Good
(2) Damaged
(3) Significantly Damaged (25% or more)
(4) No
(5) Yes (If Yes, explain under comments)
(6) Repaired
(7) Removed
(8) Encapsulated
(9) Enclosed
(7) (11) Inaccessible, no inspection data
(12) Other (Explain under comments)

psulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

District: Center Unified School District

Building: Unit X (Portable Classrooms 11-14)

School: Global Charter School (No Longer in Operation as of July 2017)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL	99	ASSUMED POSITIVE	6,000 S	CLASSROOMS 11-14	(11) DRYWALL IS ASSUMED TO EXIST BEHIND ALL DRYWALL SURFACES.	Ν
М	4" COVE BASE (BLUE) ADHESIVE	153	ASSUMED POSITIVE	120 L	CLASSROOMS 11-14	(1) (4)	Ν
М	2' X 4' CEILING PANELS	N/A	NOT SUSPECT	3,600 S	CLASSROOMS 11-14	(13) VINYL COATED FIBERGLASS PANELS	N
М	CARPET ADHESIVE	161	ASSUMED POSITIVE	3,600 S	CLASSROOMS 11-14	(1) (4)	Ν

C:Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD/20-5551 3 Yr Reinspections\Sites\Global Charter School\Global Charter HMR.wpd

CONDITION CODE

General Condition:	1) Good (2) Damaged (3) Significantly Damaged (25% or more)	
Change in Condition:	4) No (5) Yes (If Yes, explain under comments)	
Abated:	6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted	
Miscellaneous:	11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not	Inspected

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

District: Center Unified School District

Building: Unit Y (Portable Classrooms 40-43)


School: Global Charter School (No Longer in Operation as of July 2017)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL	99	ASSUMED POSITIVE	6,000 S	CLASSROOMS 40-43	(11) DRYWALL IS ASSUMED TO EXIST BEHIND ALL DRYWALL SURFACES.	Ν
М	4" COVE BASE (BROWN) ADHESIVE	139	ASSUMED POSITIVE	200 L	CLASSROOM 41	(1) (4)	Ν
М	2' X 4' CEILING PANELS (FISSURE PATTERN)	140	ASSUMED POSITIVE	900 S	CLASSROOM 41	(1) (4)	Ν
М	SHEET VINYL FLOORING (GRAY)	141	ASSUMED POSITIVE	700 S	CLASSROOM 41 & RESTROOM	(2) DAMAGED LINOLEUM IN CLASSROOM 41.	Ν
М	4" COVE BASE (BLUE) ADHESIVE	150	ASSUMED POSITIVE	360 L	CLASSROOMS 40, 42, & 43	(1) (4)	Ν
М	2' X 4' CEILING PANELS	N/A	NOT SUSPECT	2,700 S	CLASSROOMS 40, 42, & 43	(13) VINYL COATED FIBERGLASS PANELS	Ν
М	CARPET ADHESIVE	161	ASSUMED POSITIVE	3,500 S	CLASSROOMS 40-43	(1) (4)	Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Global Charter School\Global Charter HMR.wpd


CONDITION CODE

General Condition:
Change in Condition:(1) Good(2) Damaged(3) Significantly Damaged(25% or more)Abated:
Miscellaneous:(4) No(5) Yes (If Yes, explain under comments)(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & RestrictedMiscellaneous:(11) Inaccessible, no inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected



Cloud\ Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Global Charter

Project Number 20-5551



RECORD OF FRIABLE AND NON-FRIABLE ACM (FORM B)

			THRE	E-YEAR F	REINSI	PECTIO	N			
							03	CDS CODE 84-73973-6104	517	
SCHOC Mcclell	0∟ an High School							6CHOOL PHONE 916) 338-6460		
ADDRE 8725 V	SS Vatt Avenue	(NUMBER)	(STREET)		(CITY) Antelope	e, CA	(ZIP) 95843		
	completion of FC	nd functional space <u>DRM C</u> (PHYSICA e location of mater 93).	L AND HAZ	ARD ASSE	riable a SSMEI	ssumed A	RIABLE AG	CBM OR FRIA	BLÉ ASSUM	ED
				СНІ	ECK OI	NE		CHEC	K ONE	
LINE	BUILDING NAM	ME & FUNCTIONA	AL SPACE	SUR-				ACBM	ASSUME	D ACBM
	(Indicate Address i	f Different From Above))	FACING	TSI	MISC	FRIABLE	NON- FRIABLE	FRIABLE	NON- FRIABLE
1.	UNIT A-MPR			х		Х				Х
2.	UNIT B-CLASS ADMINISTRAT			х		Х		х		Х
3.	UNIT C-CLASS	SROOMS 3-6		х		Х		Х		Х
4.	UNIT D-CLASS SCIENCE ROO	SROOMS 7-12 & DM		х		х		х		х
5.	UNIT E-STOR	AGE	NO ACBM							
6.	WEIGHT ROO	M		х		Х				Х
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.	rt/Entek Consulting Group In	c\Entekgroup - Documents\Clie	nte\Center LISD\20 E	551 3 Vr Poincese	tione\Sitoe\A		Clellan Form P	ad		
C. (USCIS/SCIDE	includes consulting droup, in	C / LINERGIOUP - DOCUMENTS/CIIE	mayoemer 030/20-5	Sor S in Reinspec	uons (Sites/II		Colonari POTTI B.W			

See attached "Homogeneous Materials Records" for all materials and their locations by building. On Form B all buildings are listed, and a summary of all non-friable and friable material is provided. Friable materials and their locations are listed separately under each building on Form B.

Date of Inspection: November 6, 2020

District: Center Unified School District

School: McClellan High School

Inspector: Matt Reilly

Building: Unit A (MPR)

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	4	NONE DETECTED	4,300 S	STORAGE, KITCHEN, PLENUM CLOSETS 1 & 2, AND WATER HEATER ROOM	(13) REPRESENTED BY SAMPLES HMS-MH-S23-04A-C COLLECTED ON 5-1-92.	Ν
М	12" CEILING TILE (1/8" HOLES) & MASTIC	19	NONE DETECTED	3,100 S	MPR	(13)	Ν
М	DRYWALL & JOINT COMPOUND	110	ASSUMED POSITIVE	200 S	STORAGE/PLENUM CLOSETS 1 & 2	(1) (4)	Ν
М	12" VINYL FLOOR TILE (LIGHT BLUE) & MASTIC	151	ASSUMED POSITIVE	2,000 S	MPR AND STORAGE/PLENUM CLOSETS 1 & 2	(1) (4)	Ν
М	6" COVE BASE (BLUE) ADHESIVE	152	ASSUMED POSITIVE	250 L	MPR AND STORAGE/PLENUM CLOSETS 1 & 2	(1) (4)	Ν
М	EPOXY FLOOR COATING (LIGHT BLUE)	153	ASSUMED POSITIVE	600 S	KITCHEN	(1) (4)	Ν
S	DRYWALL TEXTURE (ORANGE PEEL STYLE)	165	ASSUMED POSITIVE	200 S	STORAGE/PLENUM CLOSETS 1 & 2	(1)(4)	N
					C:\Users\selbert\Entek Consulting Group, Inc\Entekgr CONDITION CODE	oup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\McClellan HS\McCle	ellan HMR.wpd

<u>General Condition:</u> <u>Change in Condition:</u> Abated:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclo

Miscellaneous:

(4) No (6) Repaired (11) Inaccessible, no inspection data (9) Enclosed

(12) Other (Explain under comments)

(10) Isolated & Restricted (13) Non-Asbestos/Not Inspected

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

District: Center Unified School District

School: McClellan High School

Building: Unit B (Classrooms 0-2 & Administration Offices) Page 1 of 2

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Conditior	n: Code & Comments	Friable Yes/No
S	PLASTER	4	NONE DETECTED	3,200 S	ADMINISTRATION OFFICE, PRE-SCHOOL RESTROOMS 1 & 2, OFFICE 1, NURSES OFFICE, AND CLASSROOMS 0-2	(13)	SAMPLES HMS-MH-S23-04A-C COLLECTED ON 5-1-92.	Ν
Μ	9" VINYL FLOOR TILE (OLIVE) & MASTIC	9	6%	250 S	PRE-SCHOOL RESTROOMS 1 & 2	(1) (4) (11) (11)	COVERED WITH BLUE 12" VINYL FLOOR TILE IN PRE- SCHOOL (ROOM 0) RR2. KNOWN TO EXIST BENEATH CARPET IN ROOMS 0-2	N
Μ	12" CEILING TILE (1/8" HOLES) & MASTIC	19	NONE DETECTED	2,100 S	OFFICE AND CLASSROOMS 0-2	(13)		N
Μ	DRYWALL & JOINT COMPOUND	112	ASSUMED POSITIVE	100 S	STAFF ROOMS	(1) (4)		Ν
Μ	6" COVE BASE (BLUE) ADHESIVE	154	ASSUMED POSITIVE	400 L	ADMINISTRATION OFFICE, OFFICE 1, COPY ROOM, STAFF LOUNGE, AND CLASSROOMS 0-2	(1) (4)		Ν
Μ	6" COVE BASE (GRAY) ADHESIVE	155	ASSUMED POSITIVE	40 L	NURSE OFFICE	(1) (4)		N

CONDITION CODE

General Condition: Change in Condition: Abated: Miscellaneous:

(4) No

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (1) (1) Good

(9) Enclosed (10) Isolated & Restricted

(6) Repaired (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

District: Center Unified School District

School: McClellan High School

Building: Unit B (Classrooms 0-2 & Administration Offices) Page 2 of 2

							aye z ui z
Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" VINYL FLOOR TILE (WHITE/BLUE) & MASTIC	156	ASSUMED POSITIVE	800 S	CLASSROOM 0-2	(1) (4)	Ν
М	12" VINYL FLOOR TILE (BLUE) & MASTIC	166	ASSUMED POSITIVE	300 S	OFFICE, STAFF ROOMS, NURSE OFFICE, AND PRE-SCHOOL RR2	(1) (4)	Ν
S	DRYWALL TEXTURE (KNOCKDOWN STYLE)	167	ASSUMED POSITIVE	1,000 S	STAFF ROOMS	(1) (4)	Ν
S	TEXTURE ON PLASTER	168	ASSUMED POSITIVE	3,200 S	CLASSROOMS 0-2	(1) (4)	Ν
М	CARPET ADHESIVE	174	ASSUMED POSITIVE	800 S	ADMINISTRATION OFFICE, PRINCIPAL, COPY ROOM & LOUNGE	(1) (4)	Ν
М	9" VINYL FLOOR TILE (BEIGE) & MASTIC	175	ASSUMED POSITIVE	9 S	ADMINISTRATION OFFICE AT STORAGE CLOSET	(1) (4) MAY BE PRESENT BENEATH CARPET FLOORING	N
м	12" CEILING TILE (FISSURE PATTERN) & MASTIC	176	ASSUMED POSITIVE	400 S			Ν

C:Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\McClellan HS\McClellan HMR.wpd CONDITION CODE

General Condition: Change in Condition:

Miscellaneous:

Abated:

(1) Good (4) No (6) Repaired

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7)

(9) Enclosed (10) Isolated & Restricted

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: November 6, 2020

District: Center Unified School District

School: McClellan High School

Building: Unit C (Classrooms 3-6)

Inspector: Matt Reilly

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	4	NONE DETECTED	5,200 S	CUSTODIAL STORAGE'S 1-3 AND BOY'S & GIRL'S RESTROOMS	(13) REPRESENTED BY SAMPLES HMS-MH-S23-04A-C COLLECTED ON 5-1-92.	Ν
М	9" VINYL FLOOR TILE (OFF WHITE) & MASTIC	10	10%	1,000 S	CLASSROOM 6	(11) COVERED WITH CARPET AND 12" FLOOR TILES.	Ν
М	12" CEILING TILE (1/8" HOLES) & MASTIC	19	NONE DETECTED	2,500 S	CLASSROOMS 3-6	(13)	Ν
М	9" VINYL FLOOR TILE & MASTIC	97	ASSUMED POSITIVE	3,000 S	CLASSROOMS 3-6	(11) COVERED WITH CARPET AND 12" FLOOR TILES.	N
М	12" VINYL FLOOR TILE (WHITE/BLUE) & MASTIC	150	ASSUMED POSITIVE	1,000 S	CLASSROOMS 3-6	(1) (4)	Ν
М	6" COVE BASE (BLACK) ADHESIVE	157	ASSUMED POSITIVE	30 L	CUSTODIAL STORAGE 3	(1) (4)	Ν
М	6" COVE BASE (BLUE) ADHESIVE	158	ASSUMED POSITIVE	480 L	CLASSROOMS 3-6	(1) (4)	Ν
S	TEXTURE ON PLASTER	169	ASSUMED POSITIVE	2,400 S	CLASSROOMS 3-6	(1) (4)	N
S	PLASTER	170	ASSUMED POSITIVE	2,400 S	CLASSROOMS 3-6	(1) (4)	Ν

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
le, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected General Condition: (1) Good (4) No (6) Repaired Change in Condition: Abated: Miscellaneous: (11) Inaccessible, no inspection data

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

District: Center Unified School District

School: McClellan High School

Building: Unit D (Classrooms 7-12 & Science Room) Pg. 1 of 2

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	11	NONE DETECTED	6,100 S	CUSTODIAL STORAGE 1, BOY'S & GIRL'S RESTROOMS, RESTROOMS 1 & 2, HALL, STORAGE 2, YARD STORAGE, AND BOILER ROOM	(13) REPRESENTED BY SAMPLES HMS-MH-S23-04A-C COLLECTED ON 5-1-92.	N
м	9" VINYL FLOOR TILE (OFF- WHITE) & MASTIC	12	6%	4,160 S	RESTROOMS 1 & 2, HALL, CLASSROOMS 8- 11, AND SCIENCE ROOM	 (2) (5) RR1, RR2, & HALL. MISSING TILES AT HALL ENTRY (11) COVERED WITH CARPET IN CLASSROOMS 8-11 AND SCIENCE ROOM. 	N
М	12" CEILING TILE (PIN DOT PATTERN) & MASTIC	19	NONE DETECTED	4,000 S	THROUGHOUT CLASSROOMS	(13)	Ν
М	12" CEILING TILE (1/8" HOLES PATTERN) & MASTIC	20	NONE DETECTED	2,200 S	THROUGHOUT CLASSROOMS	(13)	Ν
М	6" COVE BASE (BLUE) ADHESIVE	159	ASSUMED POSITIVE	230 L	SCIENCE ROOM, CLASSROOMS 8 & 12, AND ADJACENT CORRIDOR	(1) (4)	Ν
М	4" COVE BASE (BLACK) ADHESIVE	160	ASSUMED POSITIVE	840 L	HALL AND RESTROOMS 1 & 2, YARD STORAGE, AND STORAGE 2	(1) (4)	Ν
М	SHEET VINYL FLOORING (GRAY)	161	ASSUMED POSITIVE	70 S	WORK ROOM IN CLASSROOM 12	(1) (4)	Ν
М	4" COVE BASE (BLUE) ADHESIVE	162	ASSUMED POSITIVE	460 L	WORK ROOM (FKA: STAFF LOUNGE) & OFFICE IN CLASSROOM 12 AND CLASSROOMS 9, & 10	(1) (4)	N

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\McClellan HS\McClellan HMR.wpd

CONDITION CODE

<u>General Condition:</u> Change in Condition: Abated:

Miscellaneous:

(1) Good
(2) Damaged
(3) Significantly Damaged (25% or more)
(4) No
(5) Yes (If Yes, explain under comments)
(6) Repaired
(7) Removed
(8) Encapsulated
(9) Enclosed
(11) Inaccessible, no inspection data
(12) Other (Explain under comments) (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: November 6, 2020

District: Center Unified School District

Building: Unit D (Classrooms 7-12 & Science Room)

Pa. 2 of 2

Inspector: Matt Reilly

School: McClellan High School

	-	-	-	-			ry. 2 01 2
Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	163	ASSUMED POSITIVE	2,000 S	STAFF LOUNGE, OFFICE, & ADJOINING CORRIDOR IN CLASSROOM 12 AND CLASSROOM 9	(1) (4)	N
М	12" VINYL FLOOR TILE (WHITE/ BLUE) & MASTIC	164	ASSUMED POSITIVE	400 S	CLASSROOMS 7 & 10	(1) (4)	N
S	TEXTURE ON PLASTER	171	ASSUMED POSITIVE	3,600 S	THROUGHOUT CLASSROOMS	(1) (4)	N
S	PLASTER	172	ASSUMED POSITIVE	3,600 S	THROUGHOUT CLASSROOMS	(1) (4)	N
Μ	12" VINYL FLOOR TILE (WHITE MOTTLED)	177	ASSUMED POSITIVE	50 S	SINK AT ROOM 8	(1) (4)	N
					C:\Users\selbert\Entek Consulting Group, Inc\Entekg	roup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\McClellan HS\McC	lellan HMR.wpd

CONDITION CODE

General Condition: Change in Condition:

Abated:

(1) Good
(2) Damaged
(3) Significantly Damaged (25% or more)
(4) No
(5) Yes (If Yes, explain under comments)
(6) Repaired
(7) Removed
(8) Encapsulated
(9) Enclosed
(10) Isolated & Restricted
(11) Inaccessible, no inspection data
(12) Other (Explain under comments)
(13) Non-Asbestos/Not Inspected Miscellaneous:

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: Unit E (Storage)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	Condition: Code & Comments	
S	PLASTER	1	NONE DETECTED	2,500 S	THROUGHOUT	(13)	REPRESENTED BY SAMPLES HMS-MH-S23-04A-C COLLECTED ON 5-1-92.	N
М	DRYWALL & JOINT COMPOUND	3	NONE DETECTED	600 S	THROUGHOUT	(13)		N

CONDITION CODE

General Condition: Change in Condition: Abated:

Miscellaneous:

District: Center Unified School District

School: McClellan High School

(4) No (6) Repaired

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
le, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

Inspector: Matt Reilly

Building: Weight Room


District: Center Unified School District

School: McClellan High School


Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	on: Code & Comments	Friable Yes/No
Μ	DRYWALL	111	ASSUMED POSITIVE	1000 S	WEIGHT ROOM	(11)	DRYWALL IS ASSUMED POSITIVE TO EXIST BEHIND ALL WALL SURFACES.	N
Μ	12" VINYL FLOOR TILE (PURPLE) & MASTIC	112	ASSUMED POSITIVE	200 S	WEIGHT ROOM	(2) (5)	CRACKED TILES AT FREE WEIGHT AREA	N
Μ	12" VINYL FLOOR TILE (GRAY) & MASTIC	113	ASSUMED POSITIVE	120 S	WEIGHT ROOM	(2) (5)	CRACKED TILES AT FREE WEIGHT AREA	Ν
Μ	DRYWALL & JOINT COMPOUND	114	NONE DETECTED	1,400 S	WEIGHT ROOM	(13)		N
S	WALL TEXTURE (KNOCKDOWN STYLE)	173	ASSUMED POSITIVE	1,400 S	WEIGHT ROOM	(1) (4)		N
М	CARPET ADHESIVE	174	ASSUMED POSITIVE	UNDETERMINED	WEIGHT ROOM	(1)		N
					C:\Users\selbert\Entek Consulting Group, Inc\Entekgr CONDITION CODE	roup - Docume	ents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\McClellan HS\McC	lellan HMR.wpd

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7) <u>General Condition:</u> Change in Condition: (1) Good (4) No psulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected Abated: (6) Repaired (11) Inaccessible, no inspection data Miscellaneous:

McClellan High School









Center Unified School District McClellan High School 8725 Watt Avenue Antelope, CA 95843

Ψ


Ν

Entek Consulting Group, Inc. 4200 Rocklin Road, Suite 7 Rocklin, CA 95677 Map Not to Scale

Cloud\ Clients\Center USD\20-5551 3 Yr Reinspections\Sites\McClellan HS

Three-Year AHERA Reinspection Conducted by Matt Reilly On November 6, 2020 Project Number 20-5551

mo They



RECORD OF FRIABLE AND NON-FRIABLE ACM (FORM B)

		,			· · ·			
						S CODE -73973-6032	924	
SCHOC Spinell)L i (Cyril) Elementary School					HOOL PHONE 6) 338-6490		
ADDRE 3401 S	SS (NUMBER) (STREE	T)		(CITY) Antelope	e, CA	(ZIP) 95843		
	Each building and functional space with friable completion of <u>FORM C</u> (PHYSICAL AND HA2 ACBM). Indicate location of material on blues copy (Sec. 763.93).	ZARD ASSE	riable a	ssumed ANT OF FF	RIABLE ACE	M OR FRIAD	BLE ASSUM	ED
		СН	ECK OI	NE		CHEC	K ONE	
LINE	BUILDING NAME & FUNCTIONAL SPACE	SUR-			AC	BM	ASSUME	D ACBM
	(Indicate Address if Different From Above)	FACING	TSI	MISC	FRIABLE	NON- FRIABLE	FRIABLE	NON- FRIABLE
1.	A - K-1 & K-2			Х				Х
2.	B - LIBRARY AND CLASSROOMS 2-6	х		Х				Х
3.	C - ADMINISTRATION	х		Х				х
4.	FAN ROOM		х		х			
5.	CDC PORTABLES 1-3 DISTRICT MUST CERTIFY			х				Х
6.	C-TRAIN NO SUSPECT ACBM							
7.	CLASSROOM 9 (ADULT EDUCATION OFFICE) DISTRICT MUST CERTIFY							
8.	D - MPR NO ACBM							
9.	E - CLASSROOMS 34-38			Х				х
10.	G - CLASSROOMS 25-28	х		Х		х		х
11.	H - CLASSROOMS 19-24	х		Х		х		Х
12.	K - CLASSROOMS 29-33			Х				Х
13.	M - CLASSROOMS 13-17 & RESTROOMS 18			Х				Х
14.	O - CLASSROOMS 10-12	х		х				х
15.	C-TRAIN NO SUSPECT ACBM							
16.								
17.								

See attached "Homogeneous Materials Records" for all materials and their locations by building. On Form B all buildings are listed and a summary of all non-friable and friable material is provided. Friable materials and their locations are listed separately under each building on Form B. C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Spinelli ES\Spinelli Form B.wpd

District: Center Unified School District

School: Spinelli Elementary School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: A (K-1 & K-2)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	1	NONE DETECTED	70 S	KINDERGARTEN RESTROOMS	(13) SAMPLE HMS-SE-S23-01B COLLECTED ON 5-8-92.	Ν
М	12" CEILING TILE (1/8" HOLES)	20	NONE DETECTED	2,400 S	KINDERGARTEN CLASSROOMS	(13) REPRESENTED BY SAMPLES HMS-CCSE- C506-20A-C COLLECTED ON 5-16-95.	Ν
М	DRYWALL & JOINT COMPOUND	25	ASSUMED POSITIVE	1,860 S	THROUGHOUT	(1) (4)	Ν
М	12" VINYL FLOOR TILE (GRAY MOTTLED) & MASTIC	191	ASSUMED POSITIVE	480 S	К-1 & К-2	(1) (4)	Ν
М	6" COVE BASE (GRAY) ADHESIVE	192	ASSUMED POSITIVE	240 L	K-1 & K-2	(1) (4)	Ν
М	CARPET ADHESIVE	193	ASSUMED POSITIVE	1,400 S	K-1 & K-2	(1) (4)	Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Spinelli ES\Spinelli HMR.wpd CONDITION CODE

<u>General Condition:</u> Change in Condition:

Abated:

(1) Good (2) Damage (4) No (5) Yes (If Y

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Center Unified School District

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

School: Spinelli Elementary School

Building: B (Library & Classrooms B2-B6)

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	on: Code & Comments	Friable Yes/No
S	PLASTER	1	NONE DETECTED	2,200 S	RESTROOMS, BOILER, CUSTODIAL ROOM, HALL, RESTROOM, AND STORAGE'S 1 & 2	(13)	SAMPLE HMS-SE-S23-01A COLLECTED ON 5-8-92.	Ν
М	12" CEILING TILES (1/8" HOLES)	100	NONE DETECTED	6,000 S	CLASSROOMS B2-B6	(13)	REPRESENTED BY SAMPLES HMS-CCSE-C506- 20A-C COLLECTED ON 5-16-95.	Ν
М	DRYWALL & JOINT COMPOUND	154	NONE DETECTED	1,500 S	CLASSROOM B4 AND LIBRARY	(13)	SAMPLE ECG-07-737-150A COLLECTED ON 2-25-08	Ν
S	TEXTURE (KNOCKDOWN STYLE)	178	NONE DETECTED	1,500 S	CLASSROOM B4 AND B5, LIBRARY	(7) (13)	MATERIAL NOT FOUND IN ROOM B4. SAMPLES ECG-178A & B COLLECTED ON 2-25-08.	И
М	12" VINYL FLOOR TILE (GRAY MOTTLED) & MASTIC	191	ASSUMED POSITIVE	720 S	CLASSROOMS B2-B6 AT ENTRANCE, CUSTODIAN & TOILET	(1) (4)		N
М	6" COVE BASE (GRAY) ADHESIVE	192	ASSUMED POSITIVE	720 L	CLASSROOMS B1-B6	(1) (4)		Ν
М	CARPET ADHESIVE	193	ASSUMED POSITIVE	4,500 S	CLASSROOMS B1-B6	(1) (4)		Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Spinelli ES\Spinelli HMR.wpd

CONDITION CODE

General Condition: Change in Condition: Abated: Miscellaneous:

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7) (1) Good

(4) No (6) Repaired

(9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

District: Center Unified School District

School: Spinelli Elementary School

Inspector: Matt Reilly

Building: C (Administration) Page 1 of 2

Date of Inspection: November 6, 2020

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	n: Code & Comments	Friable Yes/No
S	PLASTER	1	NONE DETECTED	6,160 S	FAN ROOM AND STORAGE ROOM	(13)	SAMPLES HMS-SE-S23-01C COLLECTED ON 5-8-92 AND ECG-07-737-1A COLLECTED ON 2- 25-08.	Ν
т	MUDDED FITTINGS	7	20-30% CHRYSOTILE	2 EACH	FAN ROOM	(1) (4)	TWO MUDDED FITTINGS ARE VISIBLE. ADDITIONAL TSI IS ASSUMED TO EXIST IN WALL CAVITIES AND ATTIC SPACE SAMPLE # 07A-C	Y
							FAN ROOM ACCESS DOOR IS IN RESTROOM	
М	12" CEILING TILE (1/8" HOLES)	101	NONE DETECTED	1,200 S	ADMINISTRATION	(13)	REPRESENTED BY SAMPLES HMS-CCSE- C506-20A-C COLLECTED ON 5-16-95.	Ν
М	DRYWALL & JOINT COMPOUND	161	NONE DETECTED	4,000 S	ADMINISTRATION, OFFICE 1 & 2, NURSE'S OFFICE & RESTROOM, STORAGE ROOMS, STAFF LOUNGE, RESTROOMS 1 & 2, AND TELEPHONE EQUIPMENT ROOMS.	(13)	SAMPLES ECG-07-737-161A-C COLLECTED ON 2-25-08.	Ν
S	TEXTURE (ORANGE PEEL STYLE)	179	NONE DETECTED	3,000 S	ADMINISTRATION OFFICES	(13)	SAMPLES ECG-07-737-179A-C COLLECTED ON 2-25-08.	Ν
М	2' X 4' CEILING PANELS (FISSURE PATTERN)	180	NONE DETECTED	216 S	PRINCIPAL'S SECRETARY'S OFFICE	(13)	SAMPLES ECG-07-737-180A & B COLLECTED ON 2-25-08.	N
М	DUCT SEAM TAPE	188	NONE DETECTED	UNDETERMINED	FAN ROOM ON HVAC DUCT	(13)	SAMPLE ECG-07-737-188A COLLECTED ON 2- 25-08.	Ν
М	12" VINYL FLOOR TILE (GRAY MOTTLED) & MASTIC	191	ASSUMED POSITIVE	150 S	ADMINISTRATION ENTRANCE, NURSE ROOM, AND ELECTRICAL ROOM	(1) (4)		Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Spinelli ES\Spinelli HMR.wpd

CONDITION CODE

General Condition: Change in Condition: Abated:

Miscellaneous:

(1) Good
(2) Damaged
(3) Significantly Damaged
(25% or more)
(4) No
(5) Yes (If Yes, explain under comments)
(6) Repaired
(7) Removed
(8) Encapsulated
(9) Enclosed
(7) (11) Inaccessible, no inspection data
(12) Other (Explain under comments)

psulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Center Unified School District

School: Spinelli Elementary School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: C - Administration Page 2 of 2

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	6" COVE BASE (GRAY) ADHESIVE	192	ASSUMED POSITIVE	150 L	THROUGHOUT	(1) (4)	Ν
М	CARPET ADHESIVE	193	ASSUMED POSITIVE	1,500 S	THROUGHOUT	(1) (4)	Ν
					C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup -	Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Spinelli ES\	Spinelli HMR.wpd

CONDITION CODE

General Condition: Change in Condition: Abated: Miscellaneous:

(1) Good (4) No

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7) (6) Repaired (9) Enclosed (10) Isolated & Restricted

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

District: Center Unified School District

School: Spinelli Elementary School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: D (MPR)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	on: Code & Comments	Friable Yes/No
М	SHEET VINYL FLOORING (GRAY SAND PAPER PATTERN)	9	NONE DETECTED	1,417 S	RESTROOM/STORAGE AND KITCHEN	(13)	SAMPLES HMS-SE-S23-09A-C COLLECTED ON 5-8-92 AND ECG-07-737-9A COLLECTED ON 2-25-08.	Ν
М	DRYWALL & JOINT COMPOUND	10	NONE DETECTED	14,200 S	RESTROOM/STORAGE, STAGE, KITCHEN, AND MPR	(13)	SAMPLES HMS-SE-S23-10A-C COLLECTED ON 5-8-92 AND ECG-07-737-10A-C COLLECTED ON 2-25-08.	Ν
М	12" VINYL FLOOR TILE (BLUE & WHITE) WITH BLACK MASTIC	11	NONE DETECTED	2,829 S	MPR	(13)	SAMPLES HMS-SE-S23-11A-C COLLECTED ON 5-8-92 AND ECG-07-737-11A COLLECTED ON 2-25-08.	N
М	12" CEILING TILE	12	NONE DETECTED	3,656 S	STAGE AND MPR	(13)	SAMPLES HMS-SE-S23-12A-C COLLECTED ON 5-8-92.	Ν
М	SHEET VINYL FLOORING	13	NONE DETECTED	656 S	STAGE	(13)	SAMPLES HMS-SE-S23-13A-C COLLECTED ON 5-8-92.	N
S	DRYWALL TEXTURE	189	NONE DETECTED	UNDETERMINED	RESTROOM/STORAGE, STAGE, KITCHEN, AND MPR	(13)	SAMPLES ECG-07-737-186A-D COLLECTED ON 2-25-08.	Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Spinelli ES\Spinelli HMR.wpd

CONDITION CODE

General Condition: Change in Condition:

Miscellaneous:

Abated:

(1) Good (4) No (6) Repaired

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7) (9) Enclosed (10) Isolated & Restricted

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

District: Center Unified School District

School: Spinelli Elementary School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: E (Classrooms 34-38)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
Μ	DRYWALL & JOINT COMPOUND	50	ASSUMED POSITIVE	5,760 S	CLASSROOMS 34-38	(11) ASSUMED TO EXIST BEHIND TAG BOARD.	Ν
М	12" VINYL FLOOR TILE & MASTIC	52	ASSUMED POSITIVE	540 S	CLASSROOMS 34-38	(11) ASSUMED TO EXIST UNDER CARPET.	Ν
Μ	4" COVE BASE (BLUE) ADHESIVE	164	ASSUMED POSITIVE	600 L	CLASSROOMS 35-38	(1)	Ν
Μ	2' X 4' CEILING PANELS	183	ASSUMED POSITIVE	1,000 S	CLASSROOM 38	(1) (4) SOME CEILING PANELS HAVE WATER STAINING. NO ACTIVE WATER LEAKS OBSERVED.	Ν
Μ	CARPET ADHESIVE	193	ASSUMED POSITIVE	4,000 S	CLASSROOMS 34-38	(1)	Ν
Μ	4" COVE BASE (BLACK) ADHESIVE	194	ASSUMED POSITIVE	120 L	CLASSROOM 34	(1)	Ν
М	2'X4' CEILING PANELS	N/A	NOT SUSPECT	3,600 S	CLASSROOMS 34-37	(13) VINYL COATED FIBERGLASS PANELS	Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Spinelli ES\Spinelli HMR.wpd

CONDITION CODE

General Condition: Change in Condition:

Abated:

Miscellaneous:

(1) Good (4) No (6) Repaired

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7) (9) Enclosed (10) Isolated & Restricted

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

District: Center Unified School District

School: Spinelli Elementary School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: G (Classrooms 25-28)

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
Μ	DRYWALL & JOINT COMPOUND	10	NONE DETECTED	8,000 S	CLASSROOMS 25-28	(13) REPRESENTED BY SAMPLES HMS-SE-S23- 10A-C COLLECTED ON 5-8-92.	Ν
Μ	12" CEILING TILE (FISSURE PATTERN)	12	NONE DETECTED	3,600 S	CLASSROOMS 25-28	(13) REPRESENTED BY SAMPLES HMS-SE-S23- 12A-C COLLECTED ON 5-8-92.	Ν
Μ	12" VINYL FLOOR TILE (WHITE/GRAY) & MASTIC	14	1-5% IN MASTIC	480 S	CLASSROOMS 26 & 28	(1) (4)	Ν
М	4" COVE BASE (BLUE) ADHESIVE	166	ASSUMED POSITIVE	480 L	CLASSROOMS 25-28	(1) (4)	Ν
М	12" VINYL FLOOR TILE (LIGHT GRAY WITH RED STREAKS) & MASTIC	184	1-5% IN MASTIC	480 S	CLASSROOMS 25 & 27	(1) (4)	Ν
М	CARPET ADHESIVE	193	ASSUMED POSITIVE	3,200 S	CLASSROOMS 25-28	(1)(4)	Ν
S	WALL TEXTURE (KNOCKDOWN STYLE)	195	ASSUMED POSITIVE	UNDETERMINED	CLASSROOMS 25-28		Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Spinelli ES\Spinelli HMR.wpd

CONDITION CODE

General Condition: Change in Condition: Abated:

Miscellaneous:

(1) Good

(4) No

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7) (6) Repaired

psulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

District: Center Unified School District

School: Spinelli Elementary School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: H (Classrooms 19-24)

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
м	DRYWALL & JOINT COMPOUND	10	NONE DETECTED	15,500 S	CLASSROOMS 19-24	(13) REPRESENTED BY SAMPLES HMS-SE- S23-10A-C COLLECTED ON 5-8-92.	N
М	12" CEILING TILE (FISSURE PATTERN)	12	NONE DETECTED	5,400 S	CLASSROOMS 19-24	(13) REPRESENTED BY SAMPLES HMS-SE- S23-12A-C COLLECTED ON 5-8-92.	N
М	12" VINYL FLOOR TILE (WHITE /GRAY) & MASTIC	14	1-5% CHRYSOTILE (IN MASTIC)	720 S	CLASSROOMS 19, 21, & 23	(1) (4)	N
М	4" COVE BASE (BLUE) ADHESIVE	167	NONE DETECTED	720 L	CLASSROOMS 19-24	(13) SAMPLES ECG-07-737-167A & B COLLECTED ON 2-25-08.	N
М	12" VINYL FLOOR TILE (LIGHT GRAY WITH RED STREAKS) & MASTIC	185	1-5% CHRYSOTILE (IN MASTIC)	720 S	CLASSROOMS 20, 22, & 24	(1) (4)	Ν
S	TEXTURE (KNOCKDOWN STYLE)	186	NONE DETECTED	15,500 S	CLASSROOMS 19-24	(13) SAMPLES ECG-07-737-186A-D COLLECTED ON 2-25-08.	Ν
М	CARPET ADHESIVE	193	ASSUMED POSITIVE	4,800 S	CLASSROOMS 19-24		Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Spinelli ES\Spinelli HMR.wpd

CONDITION CODE

General Condition: Change in Condition: Abated: Miscellaneous:

(1) Good (4) No

(6) Repaired

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7)

psulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

District: Center Unified School District

School: Spinelli Elementary School

Date of Inspection: November 6, 2020

Inspector: Matt Reilly

Building: K (Classrooms 29-33)

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	17	NONE DETECTED	1,200 S	CLASSROOMS 29-33	 (13) REPRESENTED BY SAMPLE HMS-SE-S23- 17A COLLECTED ON 5-8-92. (11) DRYWALL ASSUMED TO EXIST BEHIND ALL WALL SURFACES. 	Ν
М	12" VINYL FLOOR TILE & MASTIC	121	ASSUMED POSITIVE	450 S	CLASSROOMS 29-33	(11) ASSUMED TO EXIST UNDER CARPET.	Ν
М	4" COVE BASE (BLUE) ADHESIVE	168	ASSUMED POSITIVE	600 L	CLASSROOMS 29-33	(1) (4)	Ν
М	CARPET ADHESIVE	193	ASSUMED POSITIVE	4,000 S	CLASSROOMS 29-33	(1) (4)	Ν
М	2'X4' CEILING PANELS	N/A	NOT SUSPECT	4,500 S	CLASSROOMS 29-33	(13) VINYL COATED FIBERGLASS PANELS tekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Spinelli	Ν

CONDITION CODE

<u>General Condition:</u> <u>Change in Condition:</u> Abated:

Miscellaneous:

(1) Good (4) No

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7) (6) Repaired

psulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

District: Center Unified School District

School: Spinelli Elementary School

Inspector: Matt Reilly

Date of Inspection: November 6, 2020

Building: M (Classrooms 13-17 & Restrooms 18)

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	40	ASSUMED POSITIVE	5,760 S	CLASSROOMS 13-17, RESTROOMS 18	(11) ASSUMED TO EXIST BEHIND DRYWALL.	Ν
М	4" COVE BASE (BLUE) ADHESIVE	171	ASSUMED POSITIVE	720 L	CLASSROOMS 13-17, RESTROOMS 18	(1) (4)	Ν
М	CARPET ADHESIVE	193	ASSUMED POSITIVE	4,500 S	CLASSROOMS 13-17	(1) (4)	Ν
S	CEILING TEXTURE (KNOCKDOWN STYLE)	195	ASSUMED POSITIVE	500 S	RESTROOMS 18	(1) (4)	Ν
М	2'X4' CEILING PANELS	N/A	NOT SUSPECT	4,500 S	CLASSROOMS 13-17	(13) VINYL COATED FIBERGLASS PANELS tekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Spinelli	N/A

CONDITION CODE

<u>General Condition:</u> <u>Change in Condition:</u> <u>Abated:</u> Miscellaneous: (1) Good(2) Damaged(3) Significantly Damaged (25% or more)(4) No(5) Yes (If Yes, explain under comments)

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Center Unified School District

School: Spinelli Elementary School

Inspector: Matt Reilly

Building: O (Classrooms 10-12) Page 1 of 2

Date of Inspection: November 6, 2020

							age i oi z
Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL & JOINT COMPOUND	60	NONE DETECTED	2,980 S	CLASSROOMS 10-12	 (13) SAMPLE ECG-07-737-60A COLLECTED ON 2-25-08. (11) DRYWALL ASSUMED TO EXIST BEHIND TAG BOARD IN CLASSROOMS 11 & 12. 	Ν
М	2' X 4' CEILING PANELS (FISSURE PATTERN)	61	NONE DETECTED	2,500 S	CLASSROOMS 10-12	(13) SAMPLE ECG-07-737-61A COLLECTED ON 2-25-08.	Υ
М	SHEET VINYL FLOORING (GRAY)	172	NONE DETECTED	810 S	CLASSROOM 10	(13) SAMPLE ECG-07-737-150A COLLECTED ON 2-25-08.	Ν
М	4" COVE BASE (LIGHT BROWN) ADHESIVE	173	ASSUMED POSITIVE	120 S	CLASSROOM 10	(1) (4)	Ν
М	4" COVE BASE (BLUE) ADHESIVE	175	ASSUMED POSITIVE	240 S	CLASSROOMS 11 & 12	(1) (4)	Ν
М	12" VINYL FLOOR TILE (LIGHT BROWN MOTTLED) & MASTIC	176	ASSUMED POSITIVE	120 S	CLASSROOM 12	(1)(4)	Ν

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Spinelli ES\Spinelli HMR.wpd

CONDITION CODE

General Condition: Change in Condition: Abated: Miscellaneous:

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (1) (1) Good (4) No

(6) Repaired

(9) Enclosed (10) Isolated & Restricted

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

District: Center Unified School District

School: Spinelli Elementary School

Inspector: Matt Reilly

Building: O (Classrooms 10-12) Page 2 of 2

Date of Inspection: November 6, 2020

							aye z ui z
Material Class	Material	Homo % Asb. Ft²/L.F. Lo Mat. #		Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	WALL TEXTURE (ORANGE PEEL STYLE)	187	ASSUMED POSITIVE	8,000 S	CLASSROOM 10	(1) (4)	Ν
М	12" VINYL FLOOR TILE (WHITE) & YELLOW MASTIC	190	NONE DETECTED	UNDETERMINED	CLASSROOM 12	(13) SAMPLE ECG-07-737-176A COLLECTED ON 2-25-08.	Ν
М	CARPET ADHESIVE	193	ASSUMED POSITIVE	2,500 S	CLASSROOMS 10, 11 & 12	(1) (4)	Ν
М	12" VINYL FLOOR TILE (DARK GRAY MOTTLED) & MASTIC	196	ASSUMED POSITIVE	UNDETERMINED	CLASSROOM 12	(1) (4)	Ν

C:Users/selbert/Entek Consulting Group, Inc/Entekgroup - Documents/Clients/Center USD/20-5551 3 Yr Reinspections/Sites/Spinelli ES/Spinelli HMR.wpd

CONDITION CODE

General Condition: Change in Condition: Abated: Miscellaneous:

(1) Good (4) No (6) Repaired

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7) (9) Enclosed (10) Isolated & Restricted

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

ENTEK CONSULTING GROUP, INC. ASSESSMENT OF TSI and/or FRIABLE MATERIAL

District: Center Unified	School District	Date: November 6, 2020				
School: Spinelli Elemen	tary School	Inspector: Matt Reilly				
Building & Location(s):	C - Administration, Fan Roc	om (FKA: Heater Roc	om)			
Sample #: 07A-C	% Asbestos-20-30%	6 Chrysotile	Homogeneous Mat. #: 7			
Material description: Mu	idded Fittings					
Total amount of materia	I this location: 2 EACH	Amount of friable material this location: 2 EAC				

Damage	Local	Distributed			Damaged	0 %
Type of Damage	Air Erosion	Water		Flaking		
	Deterioration		Physical		Delamination	


Probable cause(s) of damage: NO DAMAGE OBSERVED.

POTENTIAL FOR DISTURBANCE			RESPONSE ACTIONS		PREVENTIVE MEASURES		
	Н	М	L	Isolate/Restrict X F		Fix leaks	
Accessibility	ssibility X Repair/Cleanup		Repair/Cleanup		Prevent water contact	х	
Vibration	on X Enclo		Enclose		Do not drill, cut, sand, or grind	Х	
Air Erosion			Х	Remove	х	Do not affix signs	Х
Water X		Encapsulate		Avoid contact	х		
Occupancy X		O & M	х				

Significantly Damaged (Poor)			Assessment of Material Condition Damaged (Fair)					Not damaged (Good) X			
Potential Damage:	High		High	Mod	Low		High	Mod	Low		
Hazard Ranking:	1		2	3	4		5	6	7		
								Х			

Comments & Observations: The access door to the fan room is located in the restroom. Include this material on all future 6 month periodic inspections. Inform all affected personnel of the material location, condition, asbestos content and handling procedures.

C:\Users\selbert\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Center USD\20-5551 3 Yr Reinspections\Sites\Spinelli ES\Spinelli Assess 7.wpd



SUPPORT DOCUMENTATION

State of California Division of Occupational Safety and Health **Certified Asbestos Consultant**

Matt J Reilly Cor Th Name



Certification No. 18-6208 Expires on 04/18/21 This certification was issued by the Division of Occupational Senty and Health as authorized by Sections 7180 of seq. of the Business and Professions Code.